



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7471Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	790.00	790.00
2	BONNET HINGE @\$56.80	BENT	113.60	113.60
1	BONNET LOCK	TWISTED	104.50	104.50
1	FRONT GRILLE UPPER GARNISH	CRACKED	216.40	216.40
1	FRONT GRILLE BASE	CRACKED	312.50	312.50
1	HEADLAMP ASSY LH	CRACKED	2,070.60	1,979.20
1	FRONT BUMPER	DEFORMED/TORN	560.50	560.50
1	FRONT GRILLE EMBLEM	CRACKED	32.40	32.40
1	HEADLAMP LOWER BRACKET LH	CRACKED	88.50	88.50
1	BONNET LOCK BRACKET	CRACKED	97.20	97.20
	LESS 20% DISCOUNT		-	-858.96
			4,386.20	3,435.84
	<u>LABOUR</u>			
	PANEL BEATING - REPLACE FRONT BUMPER, BONNET, GRILLE ETC AND REALIGN ALL NECESSARY ITEM.		600.00	400.00
	LABOUR (RE-SPRAYING WORKS) - FRONT BUMPER, BONNET FENDER ETC.		750.00	550.00
			1,350.00	950.00
	GRAND TOTAL		5,736.20	4,385.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,500.00

Report Ref No. CS/INC24120402/Unh3m4(N)

TOTAL FOR SPARE PARTS: \$ 4,386.20 \$ 3,435.84

TOTAL FOR LABOUR : \$ 1,350.00 \$ 950.00

TOTAL REPAIR COST: \$ 5,736.20 \$ 4,385.84

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.