

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120410/AMA3Q2**Date:** 05/05/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900261854
Claimant Vehicle No :	SMX8685R	Insured Vehicle No :	GBC8628Y
Date of Loss:	18/12/2024	Nature of Claim:	TP
		Claim No:	0651336341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8685R		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI 1T32B4 (A)	Engine No:	CTH225646
Reg. Date:	16/03/2016 (Man. Year: 2015)	Chassis No:	WVGZZZ1TZFW089115
Colour:	Grey	Odometer:	87777 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,939.07	3,364.45	4,574.62	57.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	1,380.00	3,140.00	69.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,459.07	4,744.45	7,714.62	61.92
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	12,459.07	3,800.00	8,659.07	69.50
+ GST 9.00/9.00% (S\$)	1,121.32	342.00	779.32	69.50
Nett Amount (S\$)	13,580.39	4,142.00	9,438.39	69.50
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,809.25		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment:	27/12/2024	
Date Inspected:	27/12/2024 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LOGO	Not Necessary	132.00 FL	*132.00 FL
2	1		*TAILGATE EMBLEM TOURAN	Necessary	88.10 FL	*88.10 FL
3	1		*TAILGATE EMBLEM TDI	Necessary	81.90 FL	*81.90 FL
4	1		*TAILGATE INNER TRIM	Not Necessary	468.70 FL	*- FL
5	1		*TAILGATE TOP LOCK	Not Necessary	157.10 FL	*- FL
6	1		*TAILGATE LOWER LOCK	Not Necessary	77.30 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Not Necessary	429.30 FL	*- FL
8	2		*TAIL LAMP	Not Necessary	625.40 FL	*- FL
9	1		*TAIL LAMP LOWER BRACKET	Cracked	55.10 FL	*55.10 FL
10	1		*REAR BUMPER (UPPER)	Deformed	1,188.60 FL	*1,188.60 FL
11	1		*REAR BUMPER LOWER CENTER	Deformed	407.70 FL	*407.70 FL
12	2		*REAR BUMPER REFLECTOR	Not Necessary	140.80 FL	*- FL
13	1		*REAR BUMPER CENTER BEAM	Cracked	217.60 FL	*217.60 FL
14	2		*REAR BUMPER SIDE RETAINER	Not Necessary	92.40 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	657.80 FL	*- FL
16	2		*REAR FENDER INNER TRIM	Not Necessary	939.40 FL	*- FL
17	2		*REAR FENDER INNER COWLING	Not Necessary	413.60 FL	*- FL
18	1		*REAR END PANEL	Dented	698.70 FL	*698.70 FL
19	1		*REAR END PANEL TOP GARNISH	Cracked	169.40 FL	*169.40 FL
20	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	770.00 FL	*- FL
21	1		*REAR STORAGE BOX	Cracked	321.40 FL	*321.40 FL
22	1		*SET REAR BUMPER CLIP (UPPER)	Necessary	30.00 FS	*30.00 FS
23	1		*SET REAR BUMPER LOWER CENTER CLIP	Necessary	50.00 FS	*30.00 FS
24	1		*SET TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
25	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
28	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
29	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,752.30	3,700.50
- List Item Discount on L Items 10.00/10.00% (\$)	813.23	336.05
Total Parts (\$)	7,939.07	3,364.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	40.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,520.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >