



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2504503

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/07/2025
Reference CD/CTI24120412/Epa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNR 1602X
Insured Veh. XE 3950C
Claim No. SNM24D206978
Policy No. DMCVSNA00063922402
Accident Date 10/12/2024
Inspection Date 13/12/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24120412/Epa3q2(N)	
			Date: 15/07/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3950C	Veh. Inspected	SNR 1602X
	Policy No.	DMCVSNA00063922402	Coverage (\$)	0.00
	Claim No.	SNM24D206978	Excess (\$)	0.00
	Assign From		Assign Date	13/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KNAFZ411MJ5756175	Colour	WHITE
	Odometer	115630 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
	L/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/12/2024	Inspection Date	13/12/2024
	Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNR 1602X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BROKEN	698.00	665.00
2	REAR BUMPER REFLECTOR @\$151.00	NOT NECESSARY	302.00	-
2	REAR BUMPER SIDE INNER GARNISH @\$85.00	NOT NECESSARY	170.00	-
1	REAR BUMPER CENTER LOWER	BROKEN	286.00	286.00
6	REAR BUMPER BRACKET @\$35.00	BROKEN (3 PCS ONLY)	175.00	105.00
2	REAR BUMPER SIDE RETAINER @\$27.00	BROKEN	54.00	54.00
1	REAR BUMPER REINFORCEMENT	BROKEN	390.00	365.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$65.00	NOT NECESSARY	130.00	-
4	REVERSE SENSOR HOLDER @\$68.00	SERVICEABLE	272.00	-
4	REVERSE SENSOR @\$243.00	SHORTED (2 PCS ONLY)	972.00	400.00
2	REAR FENDER INNER COWLING @\$95.00	NOT NECESSARY	109.00	-
2	REAR FEDER INNER TRIM @\$185.00	NOT NECESSARY	370.00	-
2	TAIL LAMP @\$798.00	O/S BROKEN	1,596.00	798.00
2	TAIL PANEL PANEL @\$196.00	TO REPAIR SEE LABOUR	392.00	-
1	BOOTLID	DENTED	1,073.00	894.00
1	BOOT LID SPOILER	BROKEN	850.00	314.00
1	BOOT LID LOGO	NECESSARY	33.00	33.00
1	BOOT LID EMBLEM K3	NECESSARY	44.00	44.00
1	BOOT LID EMBLEM 'CERATO'	NECESSARY	43.00	43.00
2	BOOT LID LAMP @\$710.00	O/S BROKEN	1,420.00	710.00
2	BOOT LID STOPPER @\$19.00	MISSING (1 PCS ONLY)	38.00	19.00
2	BOOT LID HINGE @\$66.00	NOT NECESSARY	132.00	-
1	BOOT LID INSULATOR	NOT NECESSARY	82.00	-
1	BOOT LID WEATHERSTRIP	TORN	110.00	110.00
1	BOOT LID LOCK	BENT	117.00	117.00
1	BOOT LID LOCK BUTTON	NOT NECESSARY	118.00	-
1	BOOT LID LOWER LOCK	NOT NECESSARY	26.00	-
1	REAR NO PLATE LAMP @\$45.00	NOT NECESSARY	90.00	-

Report Ref No. CD/CTI24120412/Epa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE CAMERA	NOT NECESSARY	895.00	-
1	REAR END PANEL	DENTED	375.00	375.00
1	REAR END PANEL TOP GARNISH	CRUSHED	84.00	84.00
1	REAR FLOOR PANEL TOP BOARD	TORN	210.00	210.00
1	REAR TOOLS SPONGE	NOT NECESSARY	199.00	-
1	REAR CHASSIS MEMBER LH	NOT NECESSARY	983.00	-
1	REAR EXHAUST PIPE	DENTED	892.00	726.00
2	REAR EXHAUST PIPE MOUNTING @\$38.00	NOT NECESSARY	76.00	-
	LESS 10% DISCOUNT		-1,380.60	-635.20
			12,425.40	5,716.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER DIFFUSER (SPECAIL TYPE) (SN)	BROKEN	1,500.00	700.00
1	SET BOOT LID INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	BOOT LID EMBLEM C&C (SN)	NECESSARY	120.00	50.00
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	TRIANGLE BREAKDOWN SIGN (SN)	NOT NECESSARY	180.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	150.00	80.00
			2,380.00	860.00
	<u>LABOUR</u>			
	PANEL BEATING ,WELDING GRAZING CUT JOINT ,STRAIGHTEN ALL AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAIL PANEL PANEL .		1,800.00	900.00
	TO PUTTY ,POLISH ,SPRAY PAINT ,WAX ALL AFFECTED PANELS.		1,600.00	800.00
	TUFF COAT.		250.00	30.00
	WIRING CHECK .		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR .		350.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	30.00

Report Ref No. CD/CTI24120412/Epa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.00	30.00
	TRANSFER BOOTLID MECHANISM .		80.00	50.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	150.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,750.00	1,950.00
GRAND TOTAL			19,555.40	8,526.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00
---	--	--	--	-----------------

Report Ref No. CD/CTI24120412/Epa3q2(N)

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X




PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X




PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X



PHOTOGRAPHS FOR VEHICLE NO. : SNR 1602X

