

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24120414/KVP3E2**Date:** 08/01/2025REFERENCE

Insured/Claimant:	LIM TONG HWEE DARREN	Policy No:	MPC24A00134200
Date of Loss:	22/12/2024	Nature of Claim:	OD
		Claim No:	DMPC2401771H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1919E		
Make & Model:	TESLA MODEL Y RWD, (A)	Engine No:	HIDDEN
Reg. Date:	01/04/2024 (Man. Year: 2024)	Chassis No:	LRWYHCFS3RC465807
Colour:	Metallic Pearl White	Odometer:	11387 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 8 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,856.83	4,359.75	2,497.08	36.42
Miscellaneous Items	140.00	90.00	50.00	35.71
Labour	1,820.00	1,340.00	480.00	26.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,816.83	5,789.75	3,027.08	34.33
Approved Total (Overridden) (\$\$)		4,550.00		
(\$\$)	8,816.83	4,550.00	4,266.83	48.39
+ GST 9.00/9.00% (\$\$)	793.51	409.50	384.01	48.39
Nett Amount (\$\$)	9,610.34	4,959.50	4,650.84	48.39

INSPECTION

Date of Assignment:	27/12/2024 Present Location:	Optima Werkz Pte Ltd (HQ) Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Date Inspected:	30/12/2024 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2025)
Parts:	143	TESLA MODEL Y RWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1919E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Bonnet (WCP)	Repair	1,953.27 F	*- F
2	1		Bonnet lock (WCP)	Repair	54.20 F	*- F
3	1		Bumper bracket RH, front (WCP)	Cracked	0.93 F	*0.93 F
4	1		Bumper fog lamp cover RH (WCP)	Missing	6.54 F	*6.54 F
5	1		Bumper reinforcement, front (WCP)	Bent	299.06 F	*299.06 F
6	1		Bumper, front (WCP)	Cracked	542.06 F	*542.06 F
7	1		Fender bracket RH, front (WCP)	Repair	0.93 F	*- F
8	1		Fender moulding RH, front (WCP)	Missing	65.42 F	*65.42 F
9	1		Fender RH, front (WCP)	Buckled	495.33 F	*495.33 F
10	1		Fender shield RH, front (WCP)	Cracked	177.57 F	*177.57 F
11	1		Headlamp RH (WCP)	Cut	1,741.00 F	*1,741.00 F
12	1		*FRONT BUMPER ABSORBER FOAM (WCP)	Serviceable	46.73 F	*- F
13	1		*FRONT BUMPER LOWER REINFORCEMENT (WCP)	Bent	102.80 F	*102.80 F
14	1		*FRONT BUMPER UNDER COVER (WCP)	Cracked	336.45 F	*336.45 F
15	1		*FRONT BUMPER LOWER GRILLE (WCP)	Serviceable	186.91 F	*- F
16	1		*FRONT SUPPORT PANEL (WCP)	Cracked	158.87 F	*158.87 F
17	1		*FRONT SUPPORT PANEL UPPER BRACKET (WCP)	Repair	14.95 F	*- F
18	1		*FRONT FENDER INNER BRACKET RH (WCP)	Repair	13.08 F	*- F
19	1		*FRONT BONNET TESLA EMBLEM (WCP)	Necessary	37.38 F	*37.38 F

F=Franchise part.

Sub Total (S\$)	6,233.48	3,963.41
+ Margin on L,N Items 10.00/10.00% (S\$)	623.35	396.34
Total Parts (S\$)	6,856.83	4,359.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	FRONT FENDER INNER SHIELD CLIPS RH (NECESSARY)	40.00	40.00
3	1	FRONT NUMBER PLATE & HOLDER (SERVICEABLE)	50.00	0.00
Sub Total (S\$)			140.00	90.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,READJUST FRONT ACCIDENT AREAS.	New	700.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH & ETC.	New	700.00	600.00
3	TO DAIGNOSIS FAULT CODE & RESET MEMORY.	New	300.00	120.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM.	New	120.00	20.00
Gross Labour Cost (S\$)			1,820.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >