



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2501373

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/03/2025
Reference CD/CTI24120415/Eua3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBL 1866A
Insured Veh. CB 7929D
Claim No. SNM24D206933
Policy No. DMB1SNW00004942402
Accident Date 06/12/2024
Inspection Date 13/12/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24120415/Eua3q2(N)	
			Date: 10/03/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	CB 7929D	Veh. Inspected	GBL 1866A
	Policy No.	DMB1SNW00004942402	Coverage (\$)	0.00
	Claim No.	SNM24D206933	Excess (\$)	0.00
	Assign From		Assign Date	13/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE D	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GDH2011055837	Colour	WHITE
	Odometer	135894 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	DUNLOP	5 mm
	L/H Front Tyre	195 R15C	DUNLOP	5 mm
	R/H Rear Tyre	195 R15C	DUNLOP	5 mm
	L/H Rear Tyre	195 R15C	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/12/2024	Inspection Date	13/12/2024
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 1866A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SIDE PANEL LH	TO REPAIR SEE LABOUR	1,828.90	-
2	REAR SIDE INNER LOWER PANEL LH @\$648.30	TO REPAIR SEE LABOUR	1,296.60	-
2	REAR SIDE INNER PANEL (BIG) LH @\$1584.30	NOT NECESSARY	3,168.60	-
1	REAR SIDE PANEL AIR VENT RH LH	NOT NECESSARY	185.70	-
1	TAILGATE	DENTED	2,210.70	2,210.70
1	TAILGATE WINDSCREEN GLASS	BROKEN	1,343.60	1,343.60
1	TAILGATE OUTER MOULDING	NOT NECESSARY	364.90	-
1	TAILGATE OUTER HANDLE	CUT	97.80	97.80
2	TAILGATE NUMBER PLATE LAMP @\$65.50	NOT NECESSARY	131.00	-
1	TAILGATE LOGO	NECESSARY	70.50	70.50
2	TAILGATE DAMPER @\$127.40	NOT NECESSARY	254.80	-
2	TAILGATE CORNER GARNISH @\$185.90	NOT NECESSARY	371.80	-
2	TAILGATE STOPPER @\$24.10	NOT NECESSARY	48.20	-
2	TAILGATE HINGE @\$62.90	NOT NECESSARY	125.80	-
2	TAILGATE SIDE STOPPER @\$28.60	NOT NECESSARY	57.20	-
1	TAILGATE INNER BOARD	CRUSHED	388.70	388.70
1	TAILGATE INNER TOP GARNISH	NOT NECESSARY	215.60	-
1	TAILGATE WEATHERSTRIP	TORN	397.80	397.80
1	TAILGATE WEATHERSTRIP PROTECTOR	NOT NECESSARY	271.60	-
1	TAILGATE INNER LOCK	BENT	354.60	354.60
1	TAILGATE INNER LOCK COVER GARNISH	NOT NECESSARY	68.50	-
1	TAILGATE LOCK MOTOR	NOT NECESSARY	545.00	-
1	TAILGATE LOCK OUTER HANDLE	CUT	15.20	15.20
1	TAILGATE LOWER LOCK	NOT NECESSARY	254.10	-
1	TAILGATE THIRD BRAKE LAMP	NOT NECESSARY	386.40	-
2	TAIL LAMP @\$355.20	N/S CUT	710.40	355.20
2	TAIL LAMP PANEL LH @\$419.80	NOT NECESSARY	839.60	-
2	TAILLAMP LOWER GARNISH @\$257.40	NOT NECESSARY	514.80	-
2	TAILLAMP LOWER GARNISH RETAINER @\$53.70	NOT NECESSARY	107.40	-

Report Ref No. CD/CTI24120415/Eua3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP INNER PANEL LH	NOT NECESSARY	488.50	-
1	REAR BUMPER	DENTED	497.00	497.00
2	REAR BUMPER NUT COVER @\$28.00	NOT NECESSARY	56.00	-
1	REAR BUMPER STEP PANEL	BENT	384.60	384.60
2	REAR BUMPER SIDE RETAINER @\$47.50	NOT NECESSARY	95.00	-
1	REAR END PANEL (EXTEND)	NOT NECESSARY	428.10	-
1	REAR END PANEL (INNER)	NOT NECESSARY	1,124.80	-
1	REAR END PANEL (OUTER)	NOT NECESSARY	498.60	-
	LESS 25% DISCOUNT		-5,049.60	-1,528.93
			15,148.80	4,586.77
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
2	REAR SIDE PANEL SEALANT (INNER) @\$150.00 (SN)	NOT NECESSARY	300.00	-
2	REAR SIDE PANEL SEALANT (OUTER) @\$150.00 (SN)	NOT NECESSARY	300.00	-
2	REAR SIDE PANEL GLASS SEALANT @\$180.00 (SN)	NOT NECESSARY	360.00	-
2	REAR SIDE PANEL GLASS INNER SHIELD @\$120.00 (SN)	NOT NECESSARY	240.00	-
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	30.00	-
1	SET TAILLAMP LOWER GARNISH CLIP (SN)	NOT NECESSARY	30.00	-
1	SET TAILGATE CENTER MOULDING CLIP (SN)	NOT NECESSARY	30.00	-
1	TAILGATE SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET TAILGATE TOP TRIM CLIP (SN)	NECESSARY	50.00	30.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	TAILGATE STICKER HIACE (SN)	NECESSARY	50.00	30.00
1	TAILGATE STICKER 70KM/H (SN)	NECESSARY	30.00	20.00
			1,720.00	110.00
	<u>LABOUR</u>			
	PANEL BEATING AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR SIDE PANEL LH AND REAR SIDE INNER LOWER PANEL LH .		2,500.00	600.00
	SPRAY PAINTING TO AFFECTED AREA .		2,000.00	500.00
	WIRING BULB CHECKING .		80.00	30.00
	TRANSFER TAILGATE MECHANISM .		80.00	50.00

Report Ref No. CD/CTI24120415/Eua3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	120.00	-
	REMOVE AND REFIX ROOF LINING .	NOT NECESSARY	100.00	-
	REMOVE AND REFIX REAR SIDE PANEL BOARD .	NOT NECESSARY	200.00	-
	REMOVE AND REFIX SLIDING DOOR AND RAILWAY .	NOT NECESSARY	200.00	-
	REMOVE AND REFIX REAR FLOOR TOP BOARD (WOODEN).	NOT NECESSARY	500.00	-
	REMOVE AND REFIX REAR WINDSCREEN.		120.00	120.00
			5,900.00	1,300.00
GRAND TOTAL			22,768.80	5,996.77

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00
---	--	--	-----------------

Report Ref No. CD/CTI24120415/Eua3q2(N)

CHEN TSUE YEE

Automotive Assessor


HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A




PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A





PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A




PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 1866A

