

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III24120417/KQP3E2**Date:** 23/01/2025REFERENCE

Insured/Claimant:	CHOO ZHAN RUI	Policy No:	D23MPCM000397		
Date of Loss:	25/12/2024	Nature of Claim:	OD	Claim No:	MPC2024D0015294

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7687T		Engine No:	A25A5312099
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID ASCENT (A)		Chassis No:	JTNB23HKX03055818
Reg. Date:	13/03/2020 (Man. Year: 2019)		Odometer:	126800 km
Colour:	Metallic Pearl White			
Engine Capacity:	2487 cc			
Market Value/New Car Price:	S\$101,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,246.00	15,047.50	3,198.50	17.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,880.00	1,770.00	38.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,896.00	17,927.50	4,968.50	21.70
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	21,396.00	16,427.50	4,968.50	23.22
+ GST 9.00/9.00% (S\$)	1,925.64	1,478.48	447.16	23.22
Nett Amount (S\$)	23,321.64	17,905.98	5,415.66	23.22

INSPECTION

Date of Assignment: 27/12/2024

Date Inspected: 30/12/2024 Inspected At:

Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2025)
Parts:	143	TOYOTA CAMRY 2.5 HYBRID ASCENT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS7687T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	500.00 F	*500.00 F
2	1		*FRONT BONNET HINGE LH	Distorted	45.00 F	*45.00 F
3	1		*FRONT BONNET HINGE RH	Bent	45.00 F	*45.00 F
4	1		*FRONT BONNET STRUT LH	Punctured	130.00 F	*130.00 F
5	1		*FRONT BONNET STRUT RH	Punctured	130.00 F	*130.00 F
6	1		*FRONT BONNET INSULATOR	Cracked	200.00 F	*200.00 F
7	1		*FRONT BONNET LOCK	Jammed	75.00 F	*75.00 F
8	1		*FRONT UPPER GRILLE ASSEMBLY	Cracked	380.00 F	*380.00 F
9	1		*FRONT HEADLAMP LH	Broken	980.00 F	*980.00 F
10	1		*FRONT BUMPER	Torn	300.00 F	*300.00 F
11	1		*FRONT BUMPER SIDE BRACKET RH	Cracked	50.00 F	*50.00 F
12	1		*FRONT BUMPER LOWER GRILLE	Cracked	300.00 F	*300.00 F
13	1		*FRONT BUMPER UNDER COVER	Distorted	220.00 F	*220.00 F
14	1		*FRONT BUMPER REINFORCEMENT	Bent	175.00 F	*175.00 F
15	1		*FRONT BUMPER ABSORBER FOAM	Cracked	60.00 F	*60.00 F
16	1		*FRONT WIPER WASHER TANK	Broken	90.00 F	*90.00 F
17	1		*FRONT SUPPORT PANEL	Bent	690.00 F	*690.00 F
18	1		*FRONT SUPPORT PANEL UPPER COVER	Dented	150.00 F	*150.00 F
19	1		*FRONT FENDER RH	Bent	360.00 F	*360.00 F
20	1		*FRONT FENDER HYBRID EMBLEM	Necessary	40.00 F	*40.00 F
21	1		*FRONT FENDER INNER SHIELD RH	Cracked	100.00 F	*100.00 F
22	1		*FRONT FENDER AIR GUIDE RH	Cracked	85.00 F	*85.00 F
23	1		*FRONT FENDER INNER PANEL RH	Bent	450.00 F	*450.00 F
24	1		*FRONT FENDER OUTER PANEL RH	Bent	550.00 F	*550.00 F
25	1		*FRONT ABSORBER RH	Bent	750.00 F	*95.00 F
26	1		*FRONT LOWER ARM RH	Distorted	250.00 F	*250.00 F
27	1		*FRONT KNUCKLE ARM RH	Bent	260.00 F	*260.00 F
28	1		*FRONT WHEEL BEARING RH	Necessary	300.00 F	*300.00 F
29	1		*FRONT STABILISER LINKAGE RH	Distorted	85.00 F	*85.00 F
30	1		*FRONT TIE ROD END RH	Bent	85.00 F	*85.00 F
31	1		*FRONT STEERING RACK	Bent / Jammed	2,280.00 F	*2,280.00 F
32	1		*FRONT CROSSMEMBER	Bent	1,200.00 F	*1,200.00 F
33	1		*FRONT DOOR RH	Bent	700.00 F	*700.00 F
34	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	130.00 F	*- F
35	1		*SIDE SKIRT RH	Buckled	400.00 F	*400.00 F
36	1		*FRONT BONNET INSULATOR CLIPS	Necessary	50.00 FS	*50.00 FS
37	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
38	1		*FRONT GRILLE CLIPS	Necessary	40.00 FS	*40.00 FS
39	1		*FRONT NUMBER PLATE & HOLDER	Missing	50.00 FS	*45.00 FS
40	1		*FRONT TYRE RH (30%)	Punctured	300.00 FS	*90.00 FS
41	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	40.00 FS	*40.00 FS
42	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT DRIVESHAFT RH	Bent	780.00 F	*780.00 F
44	1		*FRONT BALL JOINT RH	Bent	90.00 F	*90.00 F
45	4		*CROSSMEMBER MOUNTING	Necessary	300.00 F	*300.00 F
46	1		*HEADLAMP BALLAST RH	Cracked	360.00 F	*360.00 F
47	1		*FRONT BUZZER	Dented	85.00 F	*85.00 F
48	1		*FRONT RIM RH	Repair	1,900.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$)	16,640.00	13,710.00
+ Margin on L,N Items 10.00/10.00% (\$)	1,606.00	1,337.50
Total Parts (\$)	18,246.00	15,047.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	2,000.00	1,200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT FENDER PANEL RH, FRONT DOOR RH, SIDE SKIRT RH & ETC	New	1,500.00	1,200.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT OF FRONT DOOR RH	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT LOWER ARM RH, FRONT STEERING	New	500.00	200.00
5	TO WHEEL ALIGNMENT & BALANCING	New	80.00	80.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	300.00	120.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	150.00	20.00
Gross Labour Cost (\$\$)			4,650.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >