

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24060035/EVP3E2**Date:** 14/08/2024**REFERENCE**

Insured/Claimant:	PETER YEONG YEW CHOH	Policy No:	7220100430
Date of Loss:	08/06/2024	Nature of Claim:	OD
		Claim No:	4199527285SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA199A	Engine No:	DKY015744
Make & Model:	AUDI A6, 2.0 DESIGN TFSI (140 KW) (A)	Chassis No:	WAUZZZF28MN092720
Reg. Date:	08/09/2022 (Man. Year: 2021)	Odometer:	12048 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$215,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,183.00	11,021.60	13,161.40	54.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	2,772.00	3,080.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,035.00	13,793.60	16,241.40	54.07
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	28,435.00	12,193.60	16,241.40	57.12
+ GST 9.00/9.00% (\$\$)	2,559.15	1,097.42	1,461.73	57.12
Nett Amount (\$\$)	30,994.15	13,291.02	17,703.13	57.12

INSPECTION

Date of Assignment:	11/06/2024		
Date Inspected:	13/06/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	3,380.00 FS	*2,704.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	696.00 FS	*- FS
3	1		*FRONT BUMPER HEADLIGHT WASHER PLATE	Not Necessary	54.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTER - LH	Not Necessary	50.00 FS	*- FS
5	1		*FRONT BUMPER REINFORCEMENT - LH	Not Necessary	140.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	263.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	316.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	544.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE - LH INNER	Not Necessary	42.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE - LH OUTER	Not Necessary	33.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR - LH	Not Necessary	315.00 FS	*- FS
12	1		*FRONT PARKING AID SEAL RING (6PCS)	Not Necessary	17.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	283.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,232.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	56.00 FS	*- FS
16	1		*HEADLIGHT - LH	Cut	10,397.00 FS	*8,317.60 FS
17	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	50.00 FS	*- FS
18	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	50.00 FS	*- FS
19	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	294.00 FS	*- FS
20	1		*LIFT CYLINDER - LH	Not Necessary	238.00 FS	*- FS
21	1		*LIFT CYLINDER HOSE	Not Necessary	233.00 FS	*- FS
22	1		*LIFT CYLINDER BRACKET - LH	Not Necessary	8.00 FS	*- FS
23	1		*HEADLIGHT WASHER ELBOW FITTING	Not Necessary	36.00 FS	*- FS
24	1		*FRONT FENDER - LH	Repair	1,854.00 FS	*- FS
25	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	94.00 FS	*- FS
26	2		*DOUBLE COLLARED STUD	Not Necessary	25.00 FS	*- FS
27	1		*FRONT FENDER BRACE - LH	Not Necessary	193.00 FS	*- FS
28	1		*FRONT FENDER BRACKET - LH UPPER	Not Necessary	55.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	332.00 FS	*- FS
30	1		*FRONT WHEEL SPOILER - LH	Not Necessary	207.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
32	1		*FRONT ALUMINIUM RIM - LH	Not Necessary	2,109.00 FS	*- FS
33	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Not Necessary	5.00 FS	*- FS
34	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **24,183.00** **11,021.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			5,852.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >