7/16/24, 1:45 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24070040/TNP3M4

Date: 16/07/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAA00602 **Claimant Vehicle** SHD3081E **Insured Vehicle No:** SMY2046U

No:

Date of Loss: 29/06/2024 Nature of Claim: TP Claim No: M2403652

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD3081E Reg No:

HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) Make & Model: Engine No: G4LEKU400238 25/10/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU187307 Reg. Date:

Colour: Blue Odometer: 422361 km

Engine Capacity: 1580 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Good Pre-accident Condition: Yes **Engine Modification:** Good Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	823.92	361.00	462.92	56.19
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	780.00	690.00	90.00	11.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	1,615.92	1,063.00	552.92	34.22
Approved Total (Overridden) (S\$)	850.00		
(\$\$	1,615.92	850.00	765.92	47.40
+ GST 9.00/9.00% (S\$) 145.43	76.50	68.93	47.40
Nett Amount (S\$	1,761.35	926.50	834.85	47.40

INSPECTION

Date of Assignment: 01/07/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 02/07/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jul 2024)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3081E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL
4	1		*REAR BUMPER CTR MOULDING	Cut	451.25 FL	*451.25 FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	41.45 FL	*- FL
F=Fra	anchise	part. L=ListIter	nDisc.	_		
				Sub Total (S\$)	1,029.90	451.25
			- List Item Discount on	L Items 20.00/20.00% (S\$)	205.98	90.25
				Total Parts (S\$)	823.92	361.00
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			,
1 1 OD/TP Case (Insurer)		12.00	12.00
	Sub Total (S\$)	12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	REMOVE/ REFIX REVERSE SENSOR	New	80.00	30.00
		Gross Labour Cost (S\$)	780.00	690.00
	Poport was	unsubmitted during this print-out		

< END OF ESTIMATES >