



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2600331
3 ANSON ROAD #16-00	INV Date	14/01/2026
SPRINGLEAF TOWER	Reference	CD/CTI24120432/Kpa3q2
SINGAPORE 079909	Code	CTI
ATTN: JACQUELINE TAN		

PROFESSIONAL SERVICE FEE

Vehicle No.	SMT 2810G
Insured Veh.	GBC 3465H
Claim No.	SNM24D207294
Policy No.	DMCVSNW00034772400
Accident Date	29/11/2024
Inspection Date	27/12/2024

Description	Total
Survey Inspection	280.00
Digital Photographs	
Transportation	
Subtotal	280.00
GST (9%)	25.20
Grand Total	305.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN: JACQUELINE TAN		Ref: CD/CTI24120432/Kpa3q2(N) Date: 14/01/2026 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 3465H	Veh. Inspected	SMT 2810G
Policy No.	DMCVSNW00034772400	Coverage (\$)	0.00
Claim No.	SNM24D207294	Excess (\$)	0.00
Assign From		Assign Date	27/12/2024
2. Vehicle Particulars & Condition			
Make & Model	LEXUS UX200 (A)	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTHY35BH702021411	Colour	METALLIC GREY
Odometer	68167 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	4 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	4 mm
R/H Rear Tyre	225/50 R18	BRIDGESTONE	3 mm
L/H Rear Tyre	225/50 R18	BRIDGESTONE	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/11/2024	Inspection Date	27/12/2024
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 2810G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	3,225.00	-
1	FRONT SIDE MIRROR ASSEMBLY LH	* CHECK	1,882.00	-
1	FRONT FENDER WHEEL ARCH LH	CUT	506.00	506.00
1	FRONT RIM H	DENTED	4,002.00	4,002.00
1	FRONT ABSORBER LH	SERVICEABLE	1,040.00	-
1	FRONT KNUCKLE ARM LH	* CHECK	974.00	-
1	FRONT WHEEL BEARING LH	* CHECK	846.00	-
1	FRONT LOWER ARM LH	SERVICEABLE	1,458.00	-
1	FRONT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-1,393.30	-450.80
			12,539.70	4,057.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR INNER TRIM BOARD LH CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT FENDER WHEEL ARCH CLIPS LH (SN)	NECESSARY	40.00	40.00
			90.00	40.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRONT FENDER LH.		1,000.00	300.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT FENDER LH ,FRONT DOOR LH & ETC.		500.00	400.00
	LABOUR CHARGES TO REMOVE & REINSTALL FRONT DOOR INNER MECHANISM & ETC.	NOT NECESSARY	120.00	-
	LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM LH ,FRONT ABSORBER LH ,FRONT KNUCKLE ARM LH ,FRONT WHEEL BEARING LH ,FRONT LOWER ARM LH & ETC.	* CHECK	400.00	-
	TO WHEEL ALIGNMENT & BALANCING.		120.00	20.00
	TO DAIGNOSIS FAULT CODE & ETC.	* CHECK	150.00	-

Report Ref No. CD/CTI24120432/Kpa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING & ELECTRICAL SYSTEM.		120.00	20.00
			2,410.00	740.00
	GRAND TOTAL		15,039.70	4,837.20
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,881.80 NETT)				4,837.20

Report Ref No. CD/CTI24120432/Kpa3q2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2810G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

