

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24120434/AMA3Q2**Date:** 11/04/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0009399_02
Claimant Vehicle No : SNQ8129E **Insured Vehicle No :** GBM4598Z
 Date of Loss: 27/12/2024 Nature of Claim: TP Claim No: MFL2024D0015405

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNQ8129E**
 Make & Model: TOYOTA COROLLA AXIO, 1.5 X (A) Engine No: 2NR8670988
 Reg. Date: 18/08/2017 (Man. Year: 2016) Chassis No: NRE1610021499
 Colour: White Odometer: 108874 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,950.90	2,975.77	1,975.13	39.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,860.00	1,900.00	50.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,710.90	4,835.77	3,875.13	44.49
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	8,710.90	3,800.00	4,910.90	56.38
+ GST 9.00/9.00% (S\$)	783.98	342.00	441.98	56.38
Nett Amount (S\$)	9,494.88	4,142.00	5,352.88	56.38
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,969.25		
Global Sum Settlement (S\$)		4,950.00		

INSPECTION

Date of Assignment: 30/12/2024
 Date Inspected: 30/12/2024 Inspected At: Twincar Automotive Pte Ltd (HQ)
 2 KAKI BUKIT AVEUNE 2 #01-17
 Singapore 417921
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2025)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNQ8129E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	727.00 FL	*727.00 FL
2	1		*REAR BOOTLID AXIO EMBLEM	Necessary	42.90 FL	*42.90 FL
3	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	97.50 FL	*97.50 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	44.00 FL	*44.00 FL
5	2		*REAR BOOTLID HINGES L/R	Not Necessary	99.00 FL	*- FL
6	1		*REAR BOOTLID INNER RUBBER SIDE GUIDE	Not Necessary	18.60 FL	*- FL
7	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	396.44 FL	*- FL
8	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	50.20 FL	*- FL
9	1		*REAR BOOTLID MECHANISM LOCK	Damaged	182.25 FL	*182.25 FL
10	1		*REAR BOOTLID OUTER HANDLE	Cracked	296.00 FL	*296.00 FL
11	1		*REAR BOOTLID WEATHERSTRIP	Cut	169.45 FL	*169.45 FL
12	1		*REAR BUMPER	Deformed	1,077.00 FL	*687.00 FL
13	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	131.20 FL	*- FL
14	1		*REAR END PANEL	Dented	581.40 FL	*581.40 FL
15	1		*REAR END PANEL INNER TOP GARNISH	Deformed	201.10 FL	*201.10 FL
16	1		*REAR RH FENDER INNER TRIM	Not Necessary	561.40 FL	*- FL
17	1		*REAR RH TAILLAMP INNER PANEL	Not Necessary	110.10 FL	*- FL
18	2		*REAR TAILLAMP INNER BLACK GASKET L/R	Not Necessary	87.40 FL	*- FL
19	2		*REAR TAILLAMP L/R	Cracked	579.10 FL	*579.10 FL
20	2		*REAR TAILLAMP LOWER BRACKET L/R	Not Necessary	262.50 FL	*- FL
21	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*REAR BOOTLID NUMBER PLATE	Not Necessary	25.00 FS	*- FS
23	1		*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
24	1		*SET REAR BOOTLID OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
28	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,379.54	3,877.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,428.64	901.93
Total Parts (\$)	4,950.90	2,975.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	60.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	1,000.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	600.00
6	TO APPLY ANTI -RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			3,760.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >