

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI24120435/EQP3E2  
**Date:** 15/01/2025REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP005297
<b>Claimant Vehicle No :</b>	SHC3316J	<b>Insured Vehicle No :</b>	SMJ5497K
Date of Loss:	27/12/2024	Nature of Claim:	TP
		Claim No:	M2407609

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC3316J</b>	Engine No:	2ZR2C26673
Make & Model:	TOYOTA PRIUS TAXI, 1.8 HATCHBACK(AT) (2WD) (A)	Chassis No:	JTDKB3FU003081224
Reg. Date:	31/05/2019 (Man. Year: 2018)	Odometer:	472254 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,354.44	491.22	863.22	63.73
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,060.00	680.00	380.00	35.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,426.44</b>	<b>1,183.22</b>	<b>1,243.22</b>	<b>51.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>950.00</b>		
	<b>(S\$)</b>	2,426.44	950.00	1,476.44
	<b>+ GST 9.00/9.00% (S\$)</b>	218.38	85.50	132.88
	<b>Nett Amount (S\$)</b>	<b>2,644.82</b>	<b>1,035.50</b>	<b>1,609.32</b>

INSPECTION

Date of Assignment:	30/12/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/12/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 15 Jan 2025)

**Parts:** 144      TOYOTA PRIUS TAXI 1.8 HATCHBACK(AT)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHC3316J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	*- FL
2	1		*REAR BUMPER LOWER COVER	Cut	654.96 FL	*654.96 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
4	10		*REAR BUMPER CLIP	Not Necessary	22.00 FL	*- FL
5	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
6	1		*REAR REVERSE SENSOR	Not Necessary	135.70 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,744.02</b>	<b>654.96</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	389.58	163.74
<b>Total Parts (\$)</b>	<b>1,354.44</b>	<b>491.22</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	12.00	12.00
			<b>Sub Total (\$)</b>	<b>12.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	700.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR.	New	60.00	20.00
			<b>Gross Labour Cost (\$)</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >