

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120436/AUA3Q2
Date: 11/04/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01
Claimant Vehicle No : SNN7458C Insured Vehicle No : SLG7195X
Date of Loss: 28/12/2024 Nature of Claim: TP Claim No: MFL2024D0015415

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNN7458C
Make & Model: HONDA HR-V, 1.5 LX CVT (A) Engine No: L15B4530257
Reg. Date: 07/09/2016 (Man. Year: 2016) Chassis No: JHMRU1830GX200255
Colour: White Odometer: 150749 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,919.04	9,112.72	24,806.32	73.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,400.00	3,380.00	5,020.00	59.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,319.04	12,492.72	29,826.32	70.48
Approved Total (Overridden) (S\$)		8,600.00		
(S\$)	42,319.04	8,600.00	33,719.04	79.68
+ GST 9.00/9.00% (S\$)	3,808.71	774.00	3,034.71	79.68
Nett Amount (S\$)	46,127.75	9,374.00	36,753.75	79.68
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		10,601.25		

INSPECTION

Date of Assignment: 30/12/2024
Date Inspected: 30/12/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Mar 2025)	
Parts:	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNN7458C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	865.50 FL	*545.00 FL
2	1		*REAR BUMPER REFLECTOR	N/S Cracked	356.40 FL	*178.20 FL
3	1		*REAR BUMPER SIDE	N/S Deformed	460.00 FL	*230.00 FL
4	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	114.00 FL	*57.00 FL
5	1		*TAILGATE	Distorted	1,100.00 FL	*987.00 FL
6	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
7	1		*TAILGATE EMBLEM VEZEL	Necessary	75.50 FL	*75.50 FL
8	1		*TAILGATE OUTER GARNISH	Cracked	267.80 FL	*267.80 FL
9	1		*TAILGATE SIDE LAMP	N/S Cracked	574.80 FL	*287.40 FL
10	2		*TAILGATE DAMPER	Not Necessary	361.40 FL	*- FL
11	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
12	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
13	1		*TAILGATE WIPER HARNESS	Not Necessary	683.00 FL	*- FL
14	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
15	1		*TAILGATE TOP LOCK	Damaged	180.00 FL	*180.00 FL
16	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
17	1		*TAILGATE INNER TRIM	Cracked	263.40 FL	*263.40 FL
18	2		*TAILGATE INNER SIDE TRIM	Not Necessary	96.40 FL	*- FL
19	1		*TAILGATE INNER TOP TRIM	Not Necessary	185.20 FL	*- FL
20	1		*TAILGATE WEATHERSTRIP	Torn	168.40 FL	*168.40 FL
21	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
22	1		*TAILGATE WIPER ARM	Not Necessary	135.00 FL	*- FL
23	1		*TAILGATE WIPER MOTOR	Not Necessary	490.00 FL	*- FL
24	1		*TAILGATE HINGE	Not Necessary	95.00 FL	*- FL
25	1		*TAILGATE SPOILER	Not Necessary	810.00 FL	*- FL
26	1		*TAILGATE LOCK DETECTOR	Cracked	379.00 FL	*85.00 FL
27	1		*TAILGATE LOCK DETECTOR WIRE HARNESS	Not Necessary	358.00 FL	*- FL
28	1		*BUZZER	Cracked	109.00 FL	*65.00 FL
29	1		*BUZZER WIRE HARNESS	Not Necessary	288.50 FL	*- FL
30	1		*TAIL LAMP	N/S Cracked	1,007.80 FL	*503.90 FL
31	1		*TAIL LAMP PANEL	N/S Dented	536.00 FL	*268.00 FL
32	2		*TAIL LAMP INNER PANEL	Repair	958.00 FL	*- FL
33	2		*TAIL LAMP INNER PANEL (UPPER)	Repair	740.00 FL	*- FL
34	2		*TAIL LAMP INNER PANEL (LOWER)	Repair	958.00 FL	*- FL
35	1		*REAR FENDER	N/S Buckled	2,240.00 FL	*1,120.00 FL
36	2		*REAR FENDER INNER PANEL	Repair	1,934.00 FL	*- FL
37	1		*REAR FENDER INNER TRIM	N/S Cracked	798.20 FL	*399.10 FL
38	2		*REAR FENDER INNER UPPER TRIM	Not Necessary	432.60 FL	*- FL
39	1		*REAR FENDER COWLING	N/S Torn	300.40 FL	*150.20 FL
40	1		*REAR FENDER ARCED GARNISH	N/S Deformed	369.40 FL	*184.70 FL
41	2		*REAR FENDER DRAIN PANEL	Repair	338.60 FL	*- FL
42	1		*REAR WHEEL HOUSE PANEL	N/S Dented	1,792.60 FL	*896.30 FL
43	2		*REAR WHEEL HOUSE TOP PANEL	Repair	1,173.80 FL	*- FL
44	2		*REAR SHOCK ABSORBER	Not Necessary	964.60 FL	*- FL
45	2		*REAR DOOR	Repair	1,901.60 FL	*- FL
46	2		*REAR DOOR INNER LOCK	Not Necessary	596.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*REAR DOOR INNER TRIM	Not Necessary	1,360.00 FL	*- FL
48	2		*REAR DOOR LOCK CATCHER	Not Necessary	51.40 FL	*- FL
49	2		*REAR DOOR FRAME WEATHERSTRIP	Not Necessary	374.00 FL	*- FL
50	2		*REAR DOOR WEATHERSTRIP	Not Necessary	338.00 FL	*- FL
51	2		*REAR DOOR FRONT WEATHERSTRIP	Not Necessary	136.00 FL	*- FL
52	2		*REAR DOOR OUTER MOULDING	Not Necessary	272.00 FL	*- FL
53	2		*REAR DOOR BLACK STICKER	Not Necessary	210.00 FL	*- FL
54	4		*REAR DOOR HINGE	Not Necessary	220.00 FL	*- FL
55	2		*REAR DOOR CHECKER	Not Necessary	172.60 FL	*- FL
56	1		*REAR END PANEL	Distorted	530.00 FL	*530.00 FL
57	1		*REAR END PANEL TOP GARNISH	Deformed	146.30 FL	*146.30 FL
58	1		*REAR FLOOR PANEL	Distorted	1,130.00 FL	*1,130.00 FL
59	1		*REAR FLOOR TOWING PANEL	Distorted	545.00 FL	*545.00 FL
60	1		*REAR FLOOR BOTTOM CROSS MEMBER	Repair	250.80 FL	*- FL
61	1		*REAR FLOOR SIDE PANEL	N/S Dented	595.20 FL	*297.60 FL
62	1		*REAR FLOOR PANEL BOTTOM GARNISH	Distorted	269.00 FL	*269.00 FL
63	1		*REAR FLOOR PANEL TOP BOARD	Deformed	325.70 FL	*325.70 FL
64	1		*REAR STORAGE SPONGE	Cracked	156.40 FL	*156.40 FL
65	1		*ABS SENSOR WIRE HARNESS RH	Not Necessary	358.00 FL	*- FL
66	1		*EDLC MODULE	Not Necessary	950.80 FL	*- FL
67	1		*REAR CHASSIS MEMBER	Repair	797.40 FL	*- FL
68	1		*SET CENTER EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
69	1		*CENTER EXHAUST	Not Necessary	1,980.00 FL	*- FL
70	1		*CENTER EXHAUST INSULATOR	Not Necessary	89.00 FL	*- FL
71	1		*REAR EXHAUST INSULATOR	Not Necessary	155.00 FL	*- FL
72	1		*REAR EXHAUST PIPE	Not Necessary	980.00 FL	*- FL
73	4		*REAR EXHAUST MOUNTING	Not Necessary	117.60 FL	*- FL
74	1		*SET REAR EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
75	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
76	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
77	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
78	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
79	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
80	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	150.00 FS	*- FS
81	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
82	2		*TAIL LAMP PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
83	2		*REAR FENDER SEALANT	Necessary	300.00 FS	*60.00 FS
84	2		*SET REAR FENDER INNER TRIM CLIP	Necessary	120.00 FS	*30.00 FS
85	2		*SET REAR FENDER COWLING CLIP	Necessary	120.00 FS	*30.00 FS
86	2		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
87	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
88	1		*REAR FLOOR PANEL SEALANT	Necessary	350.00 FS	*60.00 FS
89	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
90	1		*TRIANGLE BREAKDOWN SIGN	Not Necessary	180.00 FS	*- FS
91	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
92	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
93	1		*VIDEO CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	41,628.80	11,220.90
- List Item Discount on L Items 20.00/20.00% (\$)	7,709.76	2,108.18
Total Parts (\$)	33,919.04	9,112.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	3,400.00	1,600.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
3	TUFF COAT	New	250.00	80.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	100.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
10	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
12	REMOVE AND REFIX REAR EDLC	New	150.00	60.00
13	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
14	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	80.00	60.00
15	REMOVE AND REFIX ECU AND REPROGRAMMING	New	550.00	0.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			8,400.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >