

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120438/UQP3E2
Date: 10/02/2025REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 1002502649 |
| Claimant Vehicle No : | SNG4246D | Insured Vehicle No : | FBU4824D |
| Date of Loss: | 26/12/2024 | Nature of Claim: | TP |
| | | Claim No: | 387248 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SNG4246D | Engine No: | 2ZR8086206 |
| Make & Model: | TOYOTA C-HR HYBRID, 1.8 S (A) | Chassis No: | ZYX102032132 |
| Reg. Date: | 26/12/2017 (Man. Year: 2017) | Odometer: | 119706 km |
| Colour: | White | | |
| Engine Capacity: | 1797 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 215/60 R17 | Rear Tyre Size: | 215/60 R17 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 3,531.07 | 1,061.78 | 2,469.29 | 69.93 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,500.00 | 950.00 | 550.00 | 36.67 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 5,031.07 | 2,011.78 | 3,019.29 | 60.01 |
| + GST 9.00/9.00% (S\$) | 452.80 | 181.06 | 271.74 | 60.01 |
| Nett Amount (S\$) | 5,483.87 | 2,192.84 | 3,291.03 | 60.01 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 30/12/2024 | Bluwel Automotive Service Pte Ltd (HQ) |
| Date Inspected: | 08/01/2025 Inspected At: | 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 |
| | | Autobay@Kaki Bukit |
| | | Singapore 417883 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 10 Feb 2025) |
| Parts: M1-SUV | TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SNG4246D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|--------------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Deformed / Cracked | 755.10 FL | *545.21 FL |
| 2 | 1 | | *REAR BUMPER CENTRE BLACK | Torn | 455.80 FL | *392.30 FL |
| 3 | 1 | | *REAR BUMPER BEAM | Repair | 605.40 FL | *- FL |
| 4 | 1 | | *REAR BUMPER TOW COVER | Serviceable | 38.00 FL | *- FL |
| 5 | 1 | | *REAR BUMPER REFLECTOR GARNISH O/S | Grazed | 120.00 FL | *120.00 FL |
| 6 | 2 | | *REAR BUMPER SIDE RETAINERS | Not Necessary | 130.00 FL | *- FL |
| 7 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 50.00 FN | *30.00 F |
| 8 | 1 | | *REAR END PANEL | Repair | 808.20 FL | *- FL |
| 9 | 1 | | *REAR END PANEL TOP GARNISH | Not Necessary | 362.30 FL | *- FL |
| 10 | 1 | | *REAR FENDER OUTER PROTECTOR O/S | Torn | 318.20 FL | *318.20 FL |
| 11 | 1 | | *TAILLAMP O/S | Not Necessary | 625.10 FL | *- FL |
| 12 | 1 | | *SET REAR BUMPER REVERSE SENSOR | Serviceable | 280.00 FS | *- FS |
| 13 | 1 | | *REAR END PANEL SEALANT | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 4,598.10 | 1,405.71 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,054.53 | 343.93 |
| - Nett Item Discount on N Items 25.00/0.00% (\$\$) | 12.50 | 0.00 |
| Total Parts (\$\$) | 3,531.07 | 1,061.78 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK WIRING | New | 50.00 | 20.00 |
| 2 | TO DISMANTLE & REFIX REVERSE SENSOR | New | 80.00 | 30.00 |
| 3 | TO DISMANTLE & REFIX CUSHION UPHOLSTERY | New | 120.00 | 0.00 |
| 4 | TO SPRAY RUST PROOFING | New | 50.00 | 0.00 |
| 5 | LABOUR FOR PANEL BEATING & REPLACED PARTS | New | 600.00 | 400.00 |
| 6 | TO PUTTY & SPRAY PAINTING | New | 600.00 | 500.00 |
| | | | Gross Labour Cost (\$) | 1,500.00 |
| | | | | 950.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >