

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24120440/ANP3E2**Date:** 28/05/2025REFERENCEInsured/Claimant: JADA MARINE TRADE & CONSULTANT PTE LTD
Date of Loss: 26/12/2024Policy No: 2070137233
Nature of Claim: OD Claim No: 4249604848SGDESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2418X	Engine No:	DCB127910
Make & Model:	AUDI Q8, 3.0 TFSI QU TIP (A)	Chassis No:	WAUZZZF13KD043757
Reg. Date:	22/09/2020 (Man. Year: 2019)	Odometer:	52742 km
Colour:	Black		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$240,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/45 R21	Rear Tyre Size:	285/45 R21
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,358.00	24,411.52	8,946.48	26.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,082.00	17,432.00	6,650.00	27.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	57,440.00	41,843.52	15,596.48	27.15
- Excess (\$\$)	1,400.00	1,400.00	0.00	0.00
(\$\$)	56,040.00	40,443.52	15,596.48	27.83
+ GST 9.00/9.00% (\$\$)	5,043.60	3,639.92	1,403.68	27.83
Nett Amount (\$\$)	61,083.60	44,083.44	17,000.16	27.83

INSPECTION

Date of Assignment: 30/12/2024

Date Inspected: 31/12/2024

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Cut	1,641.00 FS	*1,312.80 FS
2	1	*REAR BUMPER GUIDE SECTION - RH	Not Necessary	94.00 FS	*- FS
3	1	*REAR FENDER - RH	Dented	10,844.00 FS	*8,675.20 FS
4	1	*REAR FUEL INSERT	Not Necessary	127.00 FS	*- FS
5	1	*FUEL FILLER NECK STICKER	Not Necessary	38.00 FS	*- FS
6	1	*REAR QUARTER GLASS - RH	Necessary	1,190.00 FS	*952.00 FS
7	1	*REAR WHEEL HOUSING LINER	Not Necessary	424.00 FS	*- FS
8	1	*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
9	1	*REAR SPOILER	Not Necessary	65.00 FS	*- FS
10	2	*REAR WHEEL COVER - LH / RH	N/S Necessary / O/S Missing	892.00 FS	*712.80 FS
11	1	*REAR DOOR - RH	Dented	5,945.00 FS	*4,756.00 FS
12	1	*REAR DOOR OUTER SEAL - RH BOTTOM	Necessary	214.00 FS	*170.80 FS
13	1	*BONDING AGENT	Not Necessary	54.00 FS	*- FS
14	1	*CLEANING SOLUTION	Not Necessary	92.00 FS	*- FS
15	1	*APPLICATOR	Not Necessary	10.00 FS	*- FS
16	1	*REAR DOOR OUTER SEAL - RH REAR	Necessary	315.00 FS	*251.60 FS
17	1	*REAR DOOR OUTER SEAL - RH FRONT	Not Necessary	238.00 FS	*- FS
18	1	*REAR DOOR CATCH - RH	Necessary	154.00 FS	*122.80 FS
19	1	*REAR DOOR ATTACHMENT PARTS	Not Necessary	235.00 FS	*- FS
20	1	*REAR DOOR WHEEL COVER - RH	Cut	232.00 FS	*185.20 FS
21	1	*REAR DOOR COVER - RH	Necessary	603.00 FS	*482.40 FS
22	1	*REAR DOOR EXTERIOR HANDLE - RH	Cut	412.00 FS	*329.20 FS
23	1	*REAR DOOR HANDLE CAP - RH	Repair	56.00 FS	*- FS
24	2	*REAR DOOR HANDLE UNDERLAY - RH FRONT & REAR	Not Necessary	15.00 FS	*- FS
25	1	*REAR DOOR HANDLE HOUSING	Not Necessary	24.00 FS	*- FS
26	1	*REAR DOOR HANDLE MOUNTING BAR - RH	Not Necessary	163.00 FS	*- FS
27	1	*REAR ROOF FRAME SEAL - RH	Not Necessary	193.00 FS	*- FS
28	1	*REAR SILL PANEL SEAL - RH	Necessary	315.00 FS	*251.60 FS
29	1	*REAR WHEEL COVER - RH	Not Necessary	138.00 FS	*- FS
30	1	*REAR ALUMINIUM RIM - RH	Cut	4,217.00 FS	*3,373.60 FS
31	1	*REAR ALUMINIUM RIM RUBBER VALVE	Not Necessary	5.00 FS	*- FS
32	1	*2-PACK EPOXY ADHESIVE	Not Necessary	182.00 FS	*- FS
33	1	*ALUMINIUM POWDER	Necessary	685.00 FS	*548.00 FS
34	1	*HARDENER	Necessary	244.00 FS	*195.20 FS
35	1	*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
36	1	*METAL FILTER POWDER	Necessary	280.00 FS	*280.00 FS
37	1	*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
38	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
39	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
40	1	*SUNDRIES	Necessary	1,000.00 FS	*143.52 FS
41	1	*RHS SILL TRIM STRIP (Supplementary)	Necessary	771.00 FS	*616.80 FS
42	1	*COUNTERSUNK RIVET ORDER QTY 100 (Supplementary)(80 PCS)	Necessary	200.00 FS	*160.00 FS
43	2	*2-PACK EPOXY ADHESIVE (Supplementary)	Necessary	365.00 FS	*292.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 33,358.00 24,411.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SET UP AND PLACE VEHICLE IN ALUMINIUM BAY	New	1,800.00	1,800.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
3	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	450.00	300.00
4	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,800.00	1,800.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,800.00	1,800.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	4,800.00
7	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, REAR END PANELLING, ROOF CHANNEL, RHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, BOTH REAR WHEEL ARCH TRIMS, RHS REAR DOOR LOWER COVER, RHS REAR DOOR ARCH TRIM AND RHS REAR DOOR HANDLE	New	8,300.00	4,200.00
8	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	900.00	900.00
9	TO RENEW RHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST	New	500.00	500.00
10	TO INSTALL SOLAR FILM FOR RHS 1/4 GLASS	New	400.00	400.00
11	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			24,082.00	17,432.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >