



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNL 7612J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED / CUT	1,896.00	718.60
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	284.20	-
1	FRONT BUMPER LOWER GRILLE CHROME	SERVICEABLE	321.00	-
1	FRONT BUMPER SIDE GARNISH RH	SERVICEABLE	351.20	-
1	FRONT BUMPER SIDE RETAINER	SERVICEABLE	59.10	-
1	LED HEADLAMP WITH DRL RH	SERVICEABLE	2,758.60	-
1	HEADLAMP BRACKET RH	SERVICEABLE	150.60	-
	LESS 25% DISCOUNT		-1,455.18	-179.65
			4,365.52	538.95
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	75.00	30.00
			75.00	30.00
	<u>LABOUR</u>			
	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.		500.00	180.00
	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	NOT NECESSARY	500.00	-
	ADJUST AND FOCUS LED LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION.	NOT NECESSARY	120.00	-
	REMOVE AND INSTALL FRONT PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY INPUT TESTING.	NOT NECESSARY	180.00	-
			1,300.00	180.00
	GRAND TOTAL		5,740.52	748.95
	RECOMMENDED COST OF REPAIRS			600.00

Report Ref No. CS/LIP24120441/Knh3e2(N)

MARKET VALUE: \$139,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$90,644.00=NETT VALUE: \$48,356.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.