



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6428U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	STICKER LOGO (RR DOOR) (SN)	NECESSARY	60.00	60.00
1	MOULDING ASSY, BODY ROCKER PANEL, RH	NOT NECESSARY	649.10	-
2	PAD, RR BUMPER, RH & LH, 1 @\$4.30	NOT NECESSARY	8.60	-
2	PAD, RR BUMPER, RH & LH, 2 @\$4.30	NOT NECESSARY	8.60	-
2	PAD, RR BUMPER, RH & LH, 3 @\$4.30	NOT NECESSARY	8.60	-
3	PAD, RR BUMPER, CTR @\$2.50	NOT NECESSARY	7.50	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	127.40	-
10	CLIPS PIECE, FRT BUMPER @\$4.80	NOT NECESSARY	48.00	-
1	GUARD, RR BUMPER, LOWER	NOT NECESSARY	623.50	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	NOT NECESSARY	489.00	-
1	LENS & BODY ASSY, RR BUMPER, RH	NOT NECESSARY	544.40	-
1	COVER, REAR COMBINATION LAMP, RH	NOT NECESSARY	69.90	-
1	HINGE ASSY, REAR DOOR, UPPER RH	NOT NECESSARY	107.00	-
1	HINGE ASSY, REAR DOOR, LOWER RH	NOT NECESSARY	93.90	-
1	CHECK ASSY, REAR DOOR	NOT NECESSARY	199.40	-
1	DOOR OUTER HANDLE REAR, RH	NOT NECESSARY	105.50	-
1	LINER, REAR FENDER, RH	NOT NECESSARY	151.10	-
2	HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH	NOT NECESSARY	644.10	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	478.90	-
1	FILLER, RR BUMPER, RH	TO REPAIR SEE LABOUR	168.60	-
1	PANEL SUB-ASSY, REAR DOOR, RH	TO REPAIR SEE LABOUR	1,401.70	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR SEE LABOUR	943.10	-
1	WHEEL, DISC	TO REPAIR SEE LABOUR	2,036.30	-
			8,974.20	60.00

Report Ref No. CS/GAI24120444/Uvp3e2(N)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY, FILLER, RR BUMPER, RH, PANEL SUB-ASSY, REAR DOOR, RH, PANEL SUB-ASSY, FENDER REAR RH AND WHEEL, DISC.		1,018.00	500.00
	SPRAY PAINT.		1,794.00	700.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.		100.00	-
			3,552.00	1,200.00
	<b>GRAND TOTAL</b>		<b>12,526.20</b>	<b>1,260.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,260.00</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/GAI24120444/Uvp3e2(N)

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.