

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070042/TNP3M4**Date:** 13/09/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003232810		
Claimant Vehicle No :	GBJ4534Z	Insured Vehicle No :	SND4059T		
Date of Loss:	30/06/2024	Nature of Claim:	TP	Claim No:	365262

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ4534Z	Engine No:	1KD2848575
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y20K212809
Reg. Date:	23/04/2019 (Man. Year: 2019)	Odometer:	149085 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/R15	Rear Tyre Size:	155R12
Front Left Side:	VanTour 6 mm	Rear Left Side:	VanTour 6 mm
Front Right Side:	VanTour 6 mm	Rear Right Side:	VanTour 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,406.08	547.90	3,858.18	87.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	800.00	560.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,766.08	1,347.90	4,418.18	76.62
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	5,766.08	900.00	4,866.08	84.39

INSPECTION

Date of Assignment:	02/07/2024	TWIN WHEELS AUTO TRADING ENTERPRISE 38 WOODLANDS ROAD #03-14, WOODLANDS INDUSTRIAL PARK E1, SINGAPORE 757700
Date Inspected:	08/07/2024 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Sep 2024)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ4534Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	1,487.80 FL	*- FL
2	1		*REAR TAILGATE STICKER (NDC)	Not Necessary	100.00 FL	*- FL
3	1		*REAR TAILGATE STICKER (13PAX)	Not Necessary	20.00 FL	*- FL
4	1		*REAR TAILGATE STICKER (70KM)	Not Necessary	20.00 FL	*- FL
5	1		*REAR R/H SAFETY LOCK	Bent	243.00 FL	*243.00 FL
6	1		*REAR STOPPER	Cut	131.00 FL	*45.87 FL
7	1		*REAR STOPPER PILLA	Repair	170.00 FL	*- FL
8	1		*REAR LAMP R/H	Cracked	335.00 FL	*335.00 FL
9	1		*REAR EXHAUST BOX PIPE	Not Necessary	650.60 FL	*- FL
10	1		*REAR R/H SIDE BOARD	Repair	1,700.00 FL	*- FL
11	1		*REAR TAILGATE STICKER (DYNA)	Not Necessary	20.00 FL	*- FL
12	1		*REAR TAILGATE STICKER (TOYOTA)	Not Necessary	180.20 FL	*- FL
13	1		*REAR R/H SIDE BOARD STICKER (NOC)	Necessary	100.00 FN	*80.00 F
14	1		*SET REAR REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$\$)					5,437.60	703.87
- List Item Discount on L Items 20.00/25.00% (\$\$)					1,011.52	155.97
- Nett Item Discount on N Items 20.00/0.00% (\$\$)					20.00	0.00
Total Parts (\$\$)					4,406.08	547.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO SPRAY PAINT	New	680.00	400.00
2	LABOUR TO PANEL BEATING	New	680.00	400.00
Gross Labour Cost (S\$)			1,360.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >