

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24120448/AVP3E2**Date:** 02/04/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : GBL7594U**Insured Vehicle No :** SHD2539J

Date of Loss: 27/12/2024

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBL7594U**

Make & Model: NISSAN NV350 CARAVAN, 2.0 DX (A)

Engine No: QR20022090R

Reg. Date: 29/03/2022 (Man. Year: 2021)

Chassis No: VR2E26137923

Colour: Silver

Odometer: 87240 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Arivo 6 mm

Rear Left Side: Arivo 6 mm

Front Right Side: Arivo 6 mm

Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,317.94	7,121.24	19,196.70	72.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,100.00	2,620.00	6,480.00	71.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,417.94	9,741.24	25,676.70	72.50
Approved Total (Overridden) (S\$)		7,800.00		
(S\$)	35,417.94	7,800.00	27,617.94	77.98
+ GST 9.00/9.00% (S\$)	3,187.61	702.00	2,485.61	77.98
Nett Amount (S\$)	38,605.55	8,502.00	30,103.55	77.98

INSPECTION

Date of Assignment: 30/12/2024

Date Inspected: 30/12/2024 Inspected At:

Elite Auto Restoration Pte Ltd (HQ)
No 23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Apr 2025)	
Parts:	N/A	NISSAN NV350 CARAVAN 2.0 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL7594U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	541.00 FL	*541.00 FL
2	2		*FRONT BUMPER FOG LAMP	Not Necessary	621.80 FL	*- FL
3	2		*FRONT BUMPER FOG LAMP HOLDER GARNISH	Not Necessary	228.40 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	667.10 FL	*528.00 FL
5	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	311.20 FL	*- FL
6	1		*FRONT UNDER COVER GARNISH	Not Necessary	273.60 FL	*- FL
7	1		*FRONT GRILLE	Cracked	478.50 FL	*478.50 FL
8	1		*FRONT GRILLE LOGO	Necessary	66.50 FL	*66.50 FL
9	1		*HEADLAMP	O/S Cracked	1,078.00 FL	*539.00 FL
10	1		*FRONT PANEL	Not Necessary	1,357.50 FL	*- FL
11	1		*FRONT CENTRE EXTEND PANEL	Not Necessary	398.40 FL	*- FL
12	1		*FRONT WIPER PANEL GARNISH	Not Necessary	385.90 FL	*- FL
13	1		*FRONT WIRE HARNESS	Not Necessary	984.40 FL	*- FL
14	1		*FRONT TURBO COOLER	Not Necessary	1,194.30 FL	*- FL
15	1		*DASHBOARD LOWER COVER GARNISH LH	Not Necessary	364.60 FL	*- FL
16	1		*DASHBOARD LOWER COVER GARNISH (CENTER)	Not Necessary	296.40 FL	*- FL
17	1		*DASHBOARD CENTER BOTTOM GARNISH	Not Necessary	238.00 FL	*- FL
18	1		*GLOVE COMPARTMENT	Not Necessary	378.70 FL	*- FL
19	1		*AIR CON EVAPORATOR	Not Necessary	1,846.40 FL	*- FL
20	1		*AIR CON COOLING COIL C/W BLOWER MOTOR	Not Necessary	1,017.90 FL	*- FL
21	1		*AIRCON AIR DUCT	Not Necessary	196.30 FL	*- FL
22	2		*AIR CON PIPE	Not Necessary	758.80 FL	*- FL
23	1		*REAR BUMPER	Deformed	632.70 FL	*632.70 FL
24	1		*REAR BUMPER STEP PANEL	Dented	269.60 FL	*269.60 FL
25	6		*REAR BUMPER SIDE HOLDER CLIP	Not Necessary	45.00 FL	*- FL
26	1		*TAIL GATE	Dented	2,785.60 FL	*2,301.00 FL
27	1		*TAIL GATE LOGO	Necessary	75.00 FL	*75.00 FL
28	1		*TAIL GATE EMBLEM NV350	Necessary	89.70 FL	*89.70 FL
29	1		*TAIL GATE EMBLEM CARAVAN	Necessary	78.90 FL	*78.90 FL
30	1		*TAIL GATE OUTER MOULDING	Not Necessary	463.90 FL	*- FL
31	1		*TAIL GATE CATCH	Not Necessary	31.80 FL	*- FL
32	2		*TAIL GATE SIDE STOPPER	Not Necessary	38.00 FL	*- FL
33	2		*TAILGATE DAMPER	Not Necessary	350.80 FL	*- FL
34	1		*TAIL GATE WEATHER STRIP	Cut	269.30 FL	*269.30 FL
35	1		*TAIL GATE INNER LOCK	Damaged	394.10 FL	*394.10 FL
36	1		*TAIL GATE INNER LOCK MOTOR	Not Necessary	267.30 FL	*- FL
37	1		*TAIL LAMP	O/S Cracked	597.40 FL	*298.70 FL
38	1		*REAR END PANEL (OUTER)	Dented	461.60 FL	*461.60 FL
39	1		*REAR END PANEL (INNER)	Repair	986.70 FL	*- FL
40	1		*REAR FLOOR PANEL	Repair	1,883.20 FL	*- FL
41	1		*SPARE TYRE CHAIN	Not Necessary	294.70 FL	*- FL
42	1		*SPARE TYRE CHAIN SUPPORT MEMBER	Not Necessary	387.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
44	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
45	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*30.00 FS
46	1		*SET FRONT UNDER COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
47	1		*SET DASHBOARD CLIP	Not Necessary	150.00 FS	*- FS
48	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
49	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
50	1		*TAIL GATE SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
52	1		*SET TAIL GATE OUTER MOULDING CLIP	Not Necessary	30.00 FS	*- FS
53	1		*TAIL GATE STICKER 70KM/H	Necessary	30.00 FS	*15.00 FS
54	1		*TAIL GATE STICKER 8 PAX	Necessary	30.00 FS	*15.00 FS
55	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
56	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
57	1		*SET TAILGATE INNER TRIM (STANDARD STEEL)	Not Necessary	850.00 FS	*- FS
58	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
59	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
60	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
61	1		*REAR FLOOR WOODEN PLAIN WITH CARPET	Not Necessary	1,200.00 FS	*- FS
62	1		*REAR SPARE TYRE	Not Necessary	360.00 FS	*- FS
63	1		*REAR SPARE TYRE RIM	Not Necessary	350.00 FS	*- FS
64	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
65	1		*FLOOR PANEL TOP TRIM	Dented	350.00 FS	*180.00 FS
66	1		*LALAMOVE STICKER	Necessary	180.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,726.60	7,823.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,408.66	702.36
Total Parts (\$\$)	26,317.94	7,121.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS (FRONT)	New	1,400.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	New	1,400.00	200.00
3	WIRING CHECK (FRONT)	New	80.00	30.00
4	REFOCUS HEADLAMP BEAM (FRONT)	New	60.00	0.00
5	REMOVE AND REFIX FRONT WINDSCREEN (FRONT)	New	120.00	0.00
6	REMOVE AND REFIX TURBO COOLER (FRONT)	New	80.00	0.00
7	REMOVE AND REFIX AIR CON BLOWER AND REFILL AIR CON GAS (FRONT)	New	120.00	0.00
8	REMOVE AND REFIX FRONT DASHBOARD (FRONT)	New	650.00	0.00
9	PANEL BEATING, REMOVING AND REPLACING PARTS (REAR)	New	1,800.00	800.00
10	SPRAY PAINTING TO AFFECTED AREA (REAR)	New	1,800.00	800.00
11	TUFF COAT (REAR)	New	250.00	80.00
12	TRANSFER TAILGATE MECHANISM (REAR)	New	80.00	80.00
13	REMOVE AND REFIX TAILGATE WINDSCREEN (REAR)	New	120.00	120.00
14	REMOVE UPHOLSTERY (REAR)	New	80.00	60.00
15	REAR CHASSIS ALIGNMENT (REAR)	New	250.00	0.00
16	REMOVE AND REFIX REAR REVERSE SENSOR (REAR)	New	80.00	50.00
17	REMOVE AND REFIX REAR STANDARD STEEL PANEL (REAR)	New	550.00	0.00
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC (REAR)	New	180.00	0.00
Gross Labour Cost (\$\$)			9,100.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >