

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24120450/KMA3Q2**Date:** 05/05/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05

Claimant Vehicle No : YQ3525Y **Insured Vehicle No :** YQ8884C

Date of Loss: 28/12/2024 Nature of Claim: TP Claim No: MFL2025D0000077

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YQ3525Y**

Make & Model: MITSUBISHI CANTER, 3.0 D FEB71ER4SDEN (M) Engine No: 4P10E47716

Reg. Date: 13/04/2021 (Man. Year: 2021) Chassis No: FEB71EA35045

Colour: White Odometer: 139739 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5 Rear Tyre Size: 215/75 R17.5 (D)

Front Left Side: West Lake 9 mm Rear Left Side: Haida 9/9 mm

Front Right Side: West Lake 9 mm Rear Right Side: Haida 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,250.00	2,450.00	800.00	24.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	600.00	400.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,250.00	3,050.00	1,200.00	28.24
+ GST 9.00/9.00% (S\$)	382.50	274.50	108.00	28.24
Nett Amount (S\$)	4,632.50	3,324.50	1,308.00	28.24
+ Car Rental (3.0 x S\$200.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		3,926.68		
Global Sum Settlement (S\$)		3,920.00		

INSPECTION

Date of Assignment: 09/01/2025

Date Inspected: 09/01/2025 Inspected At: Goldbell Engineering Pte Ltd (Ang Mo Kio)
Blk 5035 Ang Mo Kio Industrial Park 2,, #01-367
Singapore 569538

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Mar 2025)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB71ER4SDEN (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ3525Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALUMINIUM COMPOSITE PANEL	Bent	2,400.00 FS	*1,600.00 FS
2	1		*COMPANY LOGO STICKER	Necessary	850.00 FS	*850.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					3,250.00	2,450.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL ALUMINIUM PIPO ON TOP AND BOTTOM TO REMOVE AND REPLACE ALUMINIUM COMPOSITE PANEL	New	1,000.00	600.00
Gross Labour Cost (\$\$)			1,000.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >