

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120451/APA3Q2**Date:** 11/04/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230067611
Claimant Vehicle No :	SLB6800R	Insured Vehicle No :	SGQ1002R
Date of Loss:	28/12/2024	Nature of Claim:	TP
		Claim No:	4453295332SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6800R		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Engine No:	1ZR557829
Reg. Date:	19/04/2016 (Man. Year: 2015)	Chassis No:	MR053REH104547168
Colour:	Brown	Odometer:	106553 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,534.47	4,507.32	8,027.15	64.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	0.00	280.00	100.00
Paintwork Labour	5,270.00	1,910.00	3,360.00	63.76
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,084.47	6,417.32	11,667.15	64.51
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	18,084.47	5,100.00	12,984.47	71.80
+ GST 9.00/9.00% (S\$)	1,627.60	459.00	1,168.60	71.80
Nett Amount (S\$)	19,712.07	5,559.00	14,153.07	71.80
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,006.25		

INSPECTION

Date of Assignment:	30/12/2024	
Date Inspected:	30/12/2024	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	515.10 FL	*515.10 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	136.20 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	240.20 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	90.10 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	395.10 FL	*395.10 FL
6	1		*BOOTLID	Buckled	756.10 FL	*756.10 FL
7	1		*BOOTLID INSULATOR	Not Necessary	176.40 FL	*- FL
8	2		*BOOTLID LAMP	Not Necessary	684.00 FL	*- FL
9	1		*BOOTLID OUTER MOULDING (CHROME)	Not Necessary	426.00 FL	*- FL
10	1		*BOOTLID DEFLECTOR	Cracked	385.00 FL	*195.00 FL
11	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
12	1		*BOOTLID EMLEM COROLLA	Necessary	70.00 FL	*70.00 FL
13	1		*BOOTLID EMLEM ALTIS	Necessary	70.00 FL	*70.00 FL
14	2		*BOOT LID HINGE	Not Necessary	140.00 FL	*- FL
15	1		*BOOTLID TOP LOCK	Damaged	318.10 FL	*318.10 FL
16	1		*BOOTLID LOWER LOCK	Not Necessary	20.00 FL	*- FL
17	4		*BOOTLID STOPPER	Not Necessary	64.00 FL	*- FL
18	1		*BOOTLID WEATHERSTRIP	Cut	195.00 FL	*195.00 FL
19	2		*TAILLAMP	Cut	930.00 FL	*930.00 FL
20	1		*TAILLAMP LOWER BRACKET	Not Necessary	230.20 FL	*- FL
21	1		*TAILLAMP LOWER PANEL LH	Not Necessary	253.40 FL	*- FL
22	1		*REAR FENDER LH	Repair	987.00 FL	*- FL
23	2		*REAR FENDER INNER COWLING	Not Necessary	700.40 FL	*- FL
24	1		*REAR FENDER INNER TRIM	N/S Torn	1,540.20 FL	*395.00 FL
25	1		*REAR FENDER AIR VENT LH	Not Necessary	68.90 FL	*- FL
26	1		*REAR WINDSCREEN	Not Necessary	1,328.10 FL	*- FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	163.00 FL	*- FL
28	1		*REAR END PANEL	Dented	695.30 FL	*695.30 FL
29	1		*REAR END PANEL TOP GARNISH	Deformed	250.10 FL	*250.10 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Deformed	271.10 FL	*271.10 FL
31	2		*REVERSE SENSOR	Damaged (2 PCS ONLY)	622.20 FL	*622.20 FL
32	1		*REVERSE CAMERA	Not Necessary	986.70 FL	*- FL
33	2		*REVERSE SENSOR HOLDER	Necessary	138.60 FL	*100.00 FL
34	1		*REVERSE SENSOR WIREHARNSS	Not Necessary	437.50 FL	*- FL
35	1		*REAR CHASSIS MEMBER LH	Repair	650.30 FL	*- FL
36	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
37	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
39	1		*SET TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
40	1		*TAILLAMP PANEL SEALANT	Not Necessary	60.00 FS	*- FS
41	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
42	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
43	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
45	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	500.00 FS	*- FS
46	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
47	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,289.30 5,973.10
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,754.83 1,465.78

Total Parts (\$\$) 12,534.47 4,507.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
12	VACUUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	New	380.00	0.00
<u>Labour Items</u>				
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			5,550.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >