

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 4185L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,250.00	-
1	REAR DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	950.00	-
1	REAR RETAINER RH (CONSISTENT)	SERVICEABLE	60.00	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	450.00	-
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	180.00	-
1	SIDE SKIRT (CONSISTENT)	SERVICEABLE	120.00	-
1	RIM (CONSISTENT)	TO REPAIR SEE LABOUR	350.00	-
1	FRONT DOOR HANDLE (CONSISTENT)	SERVICEABLE	680.00	-
1	REAR DOOR HANDLE (CONSISTENT)	SERVICEABLE	420.00	-
1	FRONT BUMPER (CONSISTENT)	DENTED / CRACKED	1,050.50	1,050.50
	LESS 10% DISCOUNT		-551.05	-
	LESS 20% DISCOUNT		-	-210.10
			4,959.45	840.40
	SPECIAL NETT ITEMS			
1	FRONT DOOR HANDLE CARBON (SN)(CONSISTENT)	NOT NECESSARY	240.00	-
1	REAR DOOR HANDLE CARBON (SN)(CONSISTENT)	NOT NECESSARY	240.00	-
			480.00	-
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH ,REAR DOOR RH,REAR FENDER RH,FRONT FENDER RH AND RIM .		700.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		900.00	800.00
	ALIGNMENT CHECK.	NOT NECESSARY	80.00	-
	WIRING CHECK.		60.00	15.00
			1,740.00	1,215.00
	GRAND TOTAL		7,179.45	2,055.40

Report Ref No. CD/HSB24120453/Kpa3q2(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CD/HSB24120453/Kpa3q2(N)

KONG SENG CHEONG

Licensed Appraiser