

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING	APORE) PTE LTD	Re	f: CD/HSB24120453/Kpa3q2(N)	
	10 MARINA BOUL #48-01 MARINA B 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Da	te: 18/03/2025	
	ATTN:KITTY		Co	de: HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1116H	Veh. Inspected	SMK 4185L	
	Policy No.	P2478218	Coverage (\$)	0.00	
	Claim No.	S3M04RF8	Excess (\$)	0.00	
	Assign From		Assign Date	30/12/2024	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GK82001433	Colour	METALLIC GREY	
	Odometer	302524 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	HANKOOK	7 mm	
	L/H Front Tyre	195/55 R15	HANKOOK	7 mm	
	R/H Rear Tyre	195/55 R15	HANKOOK	4 mm	
	L/H Rear Tyre	195/55 R15	HANKOOK	4 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	01/12/2023	Inspection Date	30/12/2024	
	Survey held at	MCGAP WORKSHOP			
	60 JALAN LAM HUAT, #05-68, CARROS CENTRE, SINGAPORE 737869				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				