



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8246U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER ASSY	TORN	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	TORN	451.25	451.25
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER BEAM	NOT NECESSARY	394.80	-
1	REAR FOG LAMP ASSY	NOT NECESSARY	201.50	-
1	ANTENNA SMARTKEY	NOT NECESSARY	40.50	-
	LESS 25% DISCOUNT		-392.36	-233.16
			1,177.09	699.49
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	MALFUNCTION	180.00	180.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	55.00	40.00
			235.00	220.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	380.00
	SPRAY PAINT.		300.00	280.00
	REMOVE / REFIX REVERSE SENSOR.		50.00	30.00
			750.00	690.00
	GRAND TOTAL		2,162.09	1,609.49
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS/SMO24120457/Uqp3m4(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.