



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNM 4167S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR	DENTED	3,185.00	3,185.00
1	FRONT DOOR LOCK	NOT NECESSARY	581.00	-
1	FRONT DOOR WEATHERSTRIPE	NECESSARY	289.00	289.00
1	FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	1,055.00	-
1	FRONT DOOR GLASS REGULATOR GEAR	DAMAGED	310.00	310.00
1	FRONT DOOR GLASS REGULATOR MOTOR	NOT NECESSARY	565.00	-
	LESS 10% DISCOUNT		-598.50	-378.40
			5,386.50	3,405.60
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS.		400.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		400.00	200.00
	WIRING CHECK.	NOT NECESSARY	50.00	-
	TO TRANSFER FRONT DOOR FITTINGS.		150.00	60.00
	TO APPLY TUFF COAT.	NOT NECESSARY	150.00	-
			1,150.00	460.00
GRAND TOTAL			6,586.50	3,865.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. CS/INC24120458/Aqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 5,436.50 \$ 3,405.60

TOTAL FOR LABOUR : \$ 1,150.00 \$ 460.00

TOTAL REPAIR COST: \$ 6,586.50 \$ 3,865.60

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.