

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAI	NCE BHD		Ref:	CS3/LPC24120464/Knh3e2(N)
	300 BEACH ROAD SINGAPORE 1995) #17-04/07 THE CONCOURSE 555		Date:	14/01/2025
	ATTN: GERALD P	OH		Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YQ 6290D	Veh. Inspected		SNR 8311P
	Policy No.	Z24VC05023238	Coverage (\$)		0.00
	Claim No.		Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		30/12/2024
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH (A)	c.c		1797
	Engine No.	HIDDEN	Year of Reg.		2024
	Chassis No.	ZWR900170363	Colour		METALLIC PEARL WHITE
	Odometer	34179 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	тоуо		4 mm
	L/H Front Tyre	205/60 R16	TOYO		4 mm
	R/H Rear Tyre	205/60 R16	тоуо		4 mm
	L/H Rear Tyre	205/60 R16	TOYO		4 mm
4.	Description of Damages				
	THE VEHICLE SU	HICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	30/12/2024	Inspect Date / 7	Time	31/12/2024 (12:00 PM)
	Survey held at	T & S MOTOR SERVICE			
		BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538			
5a.	Remarks				
	A) MARKET VALUE: \$193,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$111,085=NETT VALUE: \$81,915.00 B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. D) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC24120464/Knh3e2(N)

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser