

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120465/ANP3M4**Date:** 27/03/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001385886		
Claimant Vehicle No :	SMJ3483M	Insured Vehicle No :	SMT1134G		
Date of Loss:	23/12/2024	Nature of Claim:	TP	Claim No:	386822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ3483M	Engine No:	LEB7101943
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP72001393
Reg. Date:	28/02/2019 (Man. Year: 2018)	Odometer:	171980 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	PETLAS 6 mm	Rear Left Side:	PETLAS 6 mm
Front Right Side:	PETLAS 6 mm	Rear Right Side:	PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,360.00	1,303.60	7,056.40	84.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,050.00	2,740.00	72.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,150.00	2,353.60	9,796.40	80.63
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	12,150.00	1,850.00	10,300.00	84.77
+ GST 9.00/9.00% (S\$)	1,093.50	166.50	927.00	84.77
Nett Amount (S\$)	13,243.50	2,016.50	11,227.00	84.77

INSPECTION

Date of Assignment:	31/12/2024	
Date Inspected:	31/12/2024	Inspected At: HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Mar 2025)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ3483M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,600.00 FL	*985.00 FL
2	1		*REAR BUMPER EXHAUST COVER GARNISH	Not Necessary	57.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR	O/S Cracked	98.00 FL	*49.00 FL
4	2		*REAR BUMPER REFLECTOR GARNISH	Not Necessary	136.00 FL	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	19.00 FL	*- FL
6	1		*REAR BUMPER SIDE INNER BRACKET	O/S Cracked	78.00 FL	*39.00 FL
7	1		*REAR BUMPER SPONGE	O/S Cracked	94.00 FL	*47.00 FL
8	1		*REAR BUMPER SIDE RETAINER	O/S Cracked	64.00 FL	*32.00 FL
9	1		*TAIL GATE	Repair	1,900.00 FL	*- FL
10	1		*TAIL GATE LOGO	Not Necessary	45.00 FL	*- FL
11	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	70.00 FL	*70.00 FL
12	1		*TAIL GATE EMBLEM HYBRID	Necessary	98.00 FL	*98.00 FL
13	2		*TAIL GATE STOPPER	Not Necessary	50.00 FL	*- FL
14	1		*TAIL GATE INNER LOCK	Not Necessary	190.00 FL	*- FL
15	1		*TAIL GATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
16	1		*TAIL GATE WEATHER STRIP	Not Necessary	190.00 FL	*- FL
17	1		*TAIL GATE DETECTOR	Not Necessary	296.00 FL	*- FL
18	1		*TAIL GATE INNER TRIM	Not Necessary	320.00 FL	*- FL
19	1		*TAIL GATE WINDSCREEN MOULDING	Not Necessary	160.00 FL	*- FL
20	2		*TAIL LAMP RH	Not Necessary	1,040.00 FL	*- FL
21	1		*TAIL LAMP LOWER PANEL (OUTER)	O/S Dented	544.00 FL	*272.00 FL
22	2		*REAR FENDER COWLING	Not Necessary	294.00 FL	*- FL
23	1		*REAR FENDER INNER TRIM RH	Not Necessary	550.00 FL	*- FL
24	1		*REAR FENDER AIR VENT RH	Not Necessary	58.00 FL	*- FL
25	1		*REAR END PANEL	Repair	920.00 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	155.00 FL	*- FL
27	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
28	1		*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
29	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
30	1		*TAIL GATE WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
32	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*- FS
33	2		*TAIL LAMP LOWER PANEL (OUTER) SEALANT	Not Necessary	160.00 FS	*- FS
34	1		*SET REAR FENDER INNER COWLING	Not Necessary	80.00 FS	*- FS
35	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
36	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
37	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
38	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,170.00	1,622.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,810.00	318.40
Total Parts (\$)	8,360.00	1,303.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	0.00
5	REMOVE AND REFIX REAR VIDEO RECORDER	New	80.00	0.00
6	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	0.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	0.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			3,790.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >