

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estn: \_\_\_\_\_  
 OD / TP / RES / OD RES / EVA / INV / MV  
 To in \_\_\_\_\_ vehicle No: \_\_\_\_\_  
 at W/O \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vehicle \_\_\_\_\_  
 (Policy Condition)

Veh No: 5M53483M Yr Regn: 2019 / Feb  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Shuttle Hybrid C.O. 1496  
 Colour: Blue A/C: Insured / Std / Nil / N/A  
 Sp. Reading: 171980 T/Radio: Insured / Std / Nil / N/A  
 Eng/No: \_\_\_\_\_  
 C/No: GP72001393  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/60R15  
 R: 185/60R15

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /  
 TOYO / YOKO or Petlas  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 31/12/24  
 Survey held at HP Perfect  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear o/s.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MSIG</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey: Yes (✓) No ( )</u>
	MV: _____
	PV: _____
	Nett: _____

**064 F**


Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Form ref: \_\_\_\_\_  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invo (\$ \_\_\_\_\_)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 3 + RS: \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Other \_\_\_\_\_

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778  
E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 30.12.2024

TO : **MSIG** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SMJ3483M**  
MODEL : **HONDA SHUTTLE**  
DATE OF ACCIDENT : 23.12.2024  
TIME OF ACCIDENT : 11:10 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rebrand</i>	1	\$ 1,600.00	\$ 1,600.00
2	REAR BUMPER EXHAUST COVER GARNISH	1	\$ 57.00	\$ 57.00
3	REAR BUMPER REFLECTOR <i>could RIT</i>	2	\$ 49.00	\$ 98.00
4	REAR BUMPER REFLECTOR GARNISH <i>new</i>	2	\$ 68.00	\$ 136.00
5	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 19.00	\$ 19.00
6	REAR BUMPER SIDE INNER BRACKET <i>RIT could</i>	2	\$ 39.00	\$ 78.00
7	REAR BUMPER SPONGE <i>could RIT</i>	2	\$ 47.00	\$ 94.00
8	REAR BUMPER SIDE RETAINER <i>RIT could</i>	2	\$ 32.00	\$ 64.00
9	TAIL GATE <i>Repair</i>	1	\$ 1,900.00	\$ 1,900.00
10	TAIL GATE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
11	TAIL GATE EMBLEM 'SHUTTLE' <i>yellow</i>	1	\$ 70.00	\$ 70.00
12	TAIL GATE EMBLEM 'HYBRID'	1	\$ 98.00	\$ 98.00
13	TAIL GATE STOPPER <i>new</i>	2	\$ 25.00	\$ 50.00
14	TAIL GATE INNER LOCK <i>new</i>	1	\$ 190.00	\$ 190.00
15	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 24.00	\$ 24.00
16	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 190.00	\$ 190.00
17	TAIL GATE DETECTOR <i>new</i>	1	\$ 296.00	\$ 296.00
18	TAIL GATE INNER TRIM <i>new</i>	1	\$ 320.00	\$ 320.00
19	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 160.00	\$ 160.00

985  
+  
49  
+  
+  
39  
47  
32  
+  
+  
✓  
✓  
+  
+  
+  
+  
+  
+  
+

TO : **MSIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMJ3483M**  
 MODEL : **HONDA SHUTTLE**  
 DATE OF ACCIDENT : 23.12.2024  
 TIME OF ACCIDENT : 11:10 HOURS

20	TAIL LAMP RH <i>new</i>	2	\$ 520.00	\$ 1,040.00	+
21	TAIL LAMP LOWER PANEL (OUTER) <i>RH Revert</i>	2	\$ 272.00	\$ 544.00	+ 272
22	REAR FENDER COWLING <i>new</i>	2	\$ 147.00	\$ 294.00	+
23	REAR FENDER INNER TRIM RH <i>new</i>	1	\$ 550.00	\$ 550.00	+
24	REAR FENDER AIR VENT RH <i>new</i>	1	\$ 58.00	\$ 58.00	+
25	REAR END PANEL <i>Revis</i>	1	\$ 920.00	\$ 920.00	+
26	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 155.00	\$ 155.00	+

TOTAL PRICE \$ 9,050.00  
 LESS 20% \$ 1,810.00  
**SUB TOTAL PRICE \$ 7,240.00**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
2	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
3	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	TAIL GATE WINDSCEEN SEALANT	1	\$ 80.00	\$ 80.00	+
5	TAIL GATE WINDSCEEN INNER SEAL	1	\$ 60.00	\$ 60.00	+
6	TAIL LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00	+
7	TAIL LAMP LOWER PANEL (OUTER) SELANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
8	REAR FENDER INNER COWLING (SET) <i>?</i>	1	\$ 80.00	\$ 80.00	+
9	REAR FENDER INNER TRIM CLIPS (SET) <i>?</i>	1	\$ 80.00	\$ 80.00	+
10	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	-
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
12	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	+

**TOTAL \$ 1,120.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600

TO : **MSIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SMJ3483M**  
 MODEL : **HONDA SHUTTLE**  
 DATE OF ACCIDENT : 23.12.2024  
 TIME OF ACCIDENT : 11:10 HOURS

3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	X
5	REMOVE AND REFIX REAR VIDEO RECORDER	\$ 80.00	X
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	X
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	X
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	X

**TOTAL \$ 3,790.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 8,360.00  
 TOTAL LABOUR COST : \$ 3,790.00  
 TOTAL REPAIR COST : \$ 12,150.00

*Admin Lj  
 2/2 31/12/24.  
 09 Days.*

**NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer...  
 Signature:  
 Date: