



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2712R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE (N) (DENTED)	NOT CONSISTENT WITH THE IMPACT	1,685.50	-
2	TAIL LAMP @\$315.50 (N)	N/S CRACKED / O/S NOT NECESSARY	631.00	315.50
2	TAIL LAMP BRACKET @\$125.00 (N)	NOT NECESSARY	250.00	-
1	REAR CORNER RUBBER BUSH LH (N)	TORN	25.50	25.50
1	TAIL GATE "NISSAN" STICKER (N)	NOT NECESSARY	125.50	-
	LESS 10% DISCOUNT		-271.75	-34.10
			2,445.75	306.90
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	SCRATCHED	35.00	35.00
1	SET REVERSE SENSOR (SN)	TORN	250.00	200.00
1	70KM/H STICKER (SN)	NOT NECESSARY	20.00	-
1	6 PAX STICKER (SN)	NOT NECESSARY	20.00	-
1	REAR STEP PANEL (SN)	BENT	220.00	220.00
			545.00	455.00
<u>LABOUR</u>				
	WIRE CHECKING.		20.00	20.00
	REMOVE & REFIX TAIL GATE ALUMINIUM PLATE.	NOT NECESSARY	150.00	-
	REMOVE & REFIX REAR SENSOR.	NOT NECESSARY	80.00	-
	LABOUR CHARGE.		850.00	400.00
	SPRAY PAINTING.		750.00	250.00
			1,850.00	670.00
GRAND TOTAL			4,840.75	1,431.90
RECOMMENDED COST OF REPAIRS				1,431.90

Report Ref No. CS/FCI24120466/Unp3e2(N)

MARKET VALUE: \$7,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,808.00=NETT VALUE: \$5,692.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.