



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: CAROLINE CABRERA			Ref: CS/FCI24120466/Unp3e2(N) Date: 10/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1760Y	Veh. Inspected	GBE 2712R
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D25000114MFCT	Excess (\$)	0.00
	Assign From	CAROLINE CABRERA	Assign Date	30/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR (M)	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JN1SC2F24Z0857798	Colour	SILVER
	Odometer	174388 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BLACKHAWK	6 mm
	L/H Front Tyre	195 R15	BLACKHAWK	6 mm
	R/H Rear Tyre	155 R13 (D)	BLACKHAWK	6/6 mm
	L/H Rear Tyre	155 R13 (D)	BLACKHAWK	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/12/2024	Inspection Date	03/01/2025
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	