

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24070044/TQP3E2**Date:** 28/08/2024REFERENCE

Insured/Claimant: ONG CHWEE GEOK, JENNIFER

Policy No: 2100510083

Date of Loss: 29/06/2024

Nature of Claim: OD

Claim No: 9249173169SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SCF1777T**Make & Model: AUDI Q5, 2.0 SPORT TFSI QU S TRONIC (PSR
(A)

Engine No: DAX006065

Reg. Date: 19/06/2017 (Man. Year: 2017)

Chassis No: WAUZZZF0H2025346

Colour: Black

Odometer: 94485 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$100,000.00

Price:

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17

Rear Tyre Size: 235/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,353.00	21,289.04	7,063.96	24.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,572.00	3,022.00	3,550.00	54.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,925.00	24,311.04	10,613.96	30.39
- Excess (\$\$)	1,500.00	1,500.00	0.00	0.00
(\$\$)	33,425.00	22,811.04	10,613.96	31.75
+ GST 9.00/9.00% (\$\$)	3,008.25	2,052.99	955.26	31.75
Nett Amount (\$\$)	36,433.25	24,864.03	11,569.22	31.75

INSPECTION

Date of Assignment: 02/07/2024

Date Inspected: 03/07/2024

Inspected At:

24 Benoi Sector
Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,887.00 FS	*1,509.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	361.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - LH	Deformed	48.00 FS	*37.68 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH	Deformed	141.00 FS	*112.80 FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	180.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Cut	956.00 FS	*764.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LH	Deformed	276.00 FS	*220.40 FS
8	1		*RADIATOR GRILLE	Cracked	4,344.00 FS	*3,475.20 FS
9	1		*FRONT AIR GUIDE GRILLE - LH	Deformed	735.00 FS	*588.00 FS
10	1		*FRONT AIR GUIDE GRILLE END CAP - LH	Deformed	116.00 FS	*92.40 FS
11	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Working	572.00 FS	*228.80 FS
12	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	-
13	1		*FRONT UNDERRUN BAR - SELENITE SILVER	Bent	708.00 FS	*566.00 FS
14	1		*FRONT FOAM FILLER PIECE	Deformed	223.00 FS	*178.00 FS
15	1		*FRONT REINFORCEMENT BEAM	Bent	1,195.00 FS	*956.00 FS
16	1		*OUTSIDE TEMP SENSOR BRACKET	Not Necessary	27.00 FS	*- FS
17	1		*FRONT GUIDE SECTION - LH	Deformed	49.00 FS	*38.56 FS
18	1		*LED HEADLIGHT - LH	Cracked	9,837.00 FS	*7,869.60 FS
19	1		*LED HEADLIGHT CONTROL UNIT - LH	Distorted	905.00 FS	*723.60 FS
20	1		*LED HEADLIGHT POWER MODULE - LH	Distorted	904.00 FS	*722.80 FS
21	1		*LED HEADLIGHT HEAT SINK - LH	Distorted	1,375.00 FS	*1,100.00 FS
22	1		*LIFT CYLINDER - LH	Cracked	167.00 FS	*133.60 FS
23	1		*LIFT CYLINDER HOSE	Not Necessary	159.00 FS	*- FS
24	1		*FRONT WHEEL SPOILER	Not Necessary	203.00 FS	*- FS
25	2		*FRONT WHEEL ARCH COVER - LH / RH	O/S Necessary / N/S Deformed	1,580.00 FS	*1,264.00 FS
26	1		*HORN - LH	Cracked	234.00 FS	*186.80 FS
27	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
28	1		*SUNDRIES	Necessary	600.00 FS	*61.76 FS
29	1		*HEADLIGHT MOUNTING LHS (Supplementary)	Cracked	147.00 FS	*117.60 FS
30	1		*FENDER TOP COVER LHS (Supplementary)	Deformed	50.00 FS	*39.44 FS
31	1		*RADIATOR GRILLE STRIKER PLATE (Supplementary)	Deformed	303.00 FS	*242.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 28,353.00 21,289.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS AND HEADLIGHT, HORNS OUTSIDE TEMPERATUSE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND REINSTALL FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,000.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,400.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			6,572.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >