1/20/25, 1:35 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24120467/UQP3E2

Date: 20/01/2025

REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle

No : SNB7107D Insured Vehicle No : GBD7418M

Date of Loss: 26/12/2024 Nature of Claim: TP Claim No: DMCV2400295H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNB7107D

 Make & Model:
 NISSAN NOTE, 1.2 (A)
 Engine No:
 HR12295332K

 Reg. Date:
 09/09/2021 (Man. Year: 2021)
 Chassis No:
 JN1FAAE13Z0900427

Colour: Grey Odometer: 71566 km

Engine Capacity: 1198 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R16 Rear Tyre Size: 185/60 R16
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm
Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		16,679.61	7,655.95	9,023.66	54.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,810.00	3,470.00	2,340.00	40.28
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	22.489.61	11.125.95	11.363.66	50.53

INSPECTION

Date of Assignment: 30/12/2024

Hup Motor Trading & Service (HQ)
Date Inspected:

30/12/2024 Inspected At: Blk 9004 Tampines Street 93, #01-120

Cingage F0000

Singapore 528838

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

1/20/25, 1:35 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2025)

Parts: 144 NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB7107D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DOOR	Repair	1,352.80 FN	*- FN
2	1		*TAIL GATE DOOR NOTE EMBLEM	Not Necessary	88.80 FN	*- FN
3	1		*TAIL GATE DOOR E-POWER EMBLEM	Serviceable	127.00 FN	*- FN
4	1		*TAIL GATE DOOR O/S REFLECTOR	Serviceable	237.40 FN	*- FN
5	1		*TAIL GATE DOOR INNER LOCK	Not Necessary	148.00 FN	*- FN
6	1		*REAR O/S FENDER	Distorted	1,190.40 FN	*1,190.40 FN
7	1		*REAR O/S FENDER INNER SHIELD	Torn	441.20 FN	*441.20 FN
8	10		*REAR O/S FENDER INNER SHIELD CLIPS	Necessary	60.00 FN	*60.00 FN
9	1		*REAR O/S FENDER WHEEL GARNISH	Distorted	185.40 FN	*185.40 FN
10	8		*REAR O/S FENDER WHEEL GARNISH CLIPS	Not Necessary	48.00 FN	*- FN
11	1		*REAR O/S FENDER GLASS INNER SEAL	Necessary	55.00 FN	*55.00 FN
12	1		*REAR O/S FENDER GLASS INNER DAMPER	Necessary	45.00 FN	*45.00 FN
13	1		*REAR O/S FENDER AIR SCOOP GRILLE	Twisted / Cracked	76.50 FN	*76.50 FN
14	1		*FUEL TANK LID	Broken	98.90 FN	*98.90 FN
15	1		*FUEL TANK TUBE GREMMET	Cracked	262.70 FN	*262.70 FN
16	2		*FUEL TANK TUBE GREMMET SCREW CLIPS	Necessary	38.40 FN	*38.40 FN
17	1		*O/S TAIL LAMP ASSY	Broken	374.90 FN	*374.90 FN
18	2		*O/S TAIL LAMP CLIPS STOPPER	Necessary	24.00 FN	*24.00 FN
19	1		*O/S TAIL LAMP PANEL	Badly Dented	262.00 FN	*262.00 FN
20	1		*REAR O/S DOOR	Repair	1,128.50 FN	*- FN
21	1		*REAR O/S DOOR FRAME BLACK STICKER	Not Necessary	56.00 FN	*- FN
22	1		*REAR O/S DOOR INNER LOCK	Not Necessary	191.90 FN	*- FN
23	1		*REAR O/S DOOR LOCK STRICKER	Not Necessary	45.00 FN	*- FN
24	1		*REAR O/S DOOR WEATHERSTRIP	Not Necessary	140.00 FN	*- FN
25	2		*REAR O/S DOOR TOP & LOW HINGE	Not Necessary	131.00 FN	*- FN
26	16		*REAR O/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	96.00 FN	*- FN
27	1		*REAR O/S BUMPER SIDE PAD	Distorted	508.30 FN	*508.30 FN
28	5		*REAR O/S BUMPER SIDE PAD CLIPS STOPPER	Necessary	40.00 FN	*40.00 FN
29	1		*REAR BUMPER	Torn	579.90 FN	*579.90 FN
30	10		*REAR BUMPER CLIPS	Necessary	40.00 FN	*40.00 FN
31	1		*REAR BUMPER O/S SIDE RETAINER	Cracked	38.00 FN	*38.00 FN
32	1		*REAR BUMPER O/S REFLECTOR	Missing	68.90 FN	*68.90 FN
33	1		*REAR END PANEL	Repair	758.40 FN	*- FN
34	1		*REAR END PANEL TOP GARNISH	Not Necessary	87.60 FN	*- FN
35	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FN	*- FN
36	1		*REAR O/S FENDER GLASS	Broken	534.50 FS	*534.50 FS
37	1		*REAR O/S FENDER GLASS SEALANT	Necessary	50.00 FS	*30.00 FS
38	1		*FUEL TANK TUBE PACKING NECK	Not Necessary	405.30 FS	*- FS
39	1		*FUEL TANK LOCK CAP	Damaged	48.00 FS	*48.00 FS
40	1		*SET REAR BUMPER O/S & N/S PARKING SENSOR	Broken / Missing (1Pc Only)	680.00 FS	*258.20 FS
41	1		*SET REAR BUMPER O/S & N/S REVERSE SENSOR	Not Necessary	680.00 FS	*- FS
42	1		*REAR O/S SHOCK ABSORBER SHAFT	Bent	286.60 FS	*286.60 FS
			Report was unsubmitted during			

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR O/S WHEEL BEARING & HUB COMP	Damaged	385.60 FS	*385.60 FS
44	1		*REAR O/S COIL SPRING	Not Necessary	260.60 FS	*- FS
45	1		*REAR AXLE CROSS MEMBER	Bent / Twisted	1,132.10 FS	*1,132.10 FS
46	2		*REAR O/S & N/S SPORT RIM	Repair	1,876.20 FS	*- FS
47	2		*REAR O/S & N/S WHEEL TYRE	Serviceable	1,160.00 FS	*- FS
48	1		*FUEL TANK LID LOCK ROD CONTROL SWITCH	Damaged	58.00 FN	*58.00 FN
19	1		*REAR O/S FENDER QUARTER GLASS SOLA FILM	Necessary	48.00 FN	*48.00 FN
50	1		*REAR O/S PARKING SENSOR COVER FRAME	Necessary	50.00 FN	*50.00 FN
51 ==Fra	1 inchise	part. S=Spc	*REAR O/S SAFETY BELT :Nett. N=NettItemDisc.	Activated / Damaged	890.00 FS	*890.00 FS
				Sub Total (S\$)	17,600.80	8,110.50
			- Nett Item Discount	on N Items 10.00/10.00% (S\$)	921.19	454.55
				Total Parts (S\$)	16,679.61	7,655.95
			Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TOWING CHARGE BY KING DOLLY (ATTACH BILL)	New	150.00	150.00
2	TO REMOVE & REFIX REAR CUSHION SEAT, UPHOLSTERY, SAFETY BELT, CARPET, FLOOR MAT, FLOOR BOARD COVER, SPARE TYRE, TOOL SET, GARNISH, SPARE TYRE & NECESSARY PARTS	New -	200.00	80.00
3	TO REMOVE & REFIX REAR O/S FENDER GLASS & NECESSARY PARTS	New	150.00	80.00
4	TO REMOVE & REFIX TAIL GATE DOOR INNER TRIM BOARD, REAR O/S DOOR INNER TRIM BOARD, INNER LOCK, WEATHERSTRIP, CHANNEL, HINGE & NECESSARY PARTS	New	220.00	0.00
5	TO REMOVE & REFIX FUEL TANK, TUBE, PIPE, HOSE & NECESSARY PARTS	New	200.00	60.00
6	TO REMOVE & REFIX REAR AXLE CROSS MEMBER, REAR SHOCK ABSORBER, COIL SPRING, BEARING HUB & NECESSARY PARTS	New	320.00	280.00
7	TO CHECK & ADJUST 4 WHEEL ALIGNMENT & TYRE BALANCING, USING COMPUTERISED	i New	180.00	60.00
8	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM, INCLUDING DIAGNOSE & RE-SET FAULT CODE	New	150.00	110.00
9	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	50.00
10	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR O/S WHEEL HOUSE PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	2,000.00	1,400.00
11	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	2,000.00	1,200.00
12	TO PUMP BODY SEALANT FOR AFFECTED BODY PANEL	New	120.00	0.00
	Gross Labou	r Cost (S\$)	5,810.00	3,470.00
	Report was unsubmitted during this pr	int-out.		

< END OF ESTIMATES >