



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SGW 4416D

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	805.15
1	REAR BUMPER SIDE RETAINER O/S	CRACKED	45.90
1	REAR BUMPER DIFFUSER	TWISTED	480.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	-
1	TAILLAMP O/S	BROKEN	350.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	-
	LESS 15% DISCOUNT		-252.16
			1,428.89
<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00
1	SET REAR REVERSE SENSOR (SN)	SERVICEABLE	-
			30.00
<u>LABOUR</u>			
	TO CHECK WIRING.		20.00
	TO R&R REAR REVERSE SENSOR.		30.00
	LABOUR. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR FENDER O/S.		400.00
	PAINTING.		500.00
			950.00
GRAND TOTAL			2,408.89

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	1,900.00
---	-----------------

Report Ref No. CS3/SPF24120470/Uqp3m4(N)

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.