



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF24120470/Uqp3m4(N)

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675

Date: 17/01/2025

ATTN: YAP RAY KAI JOEL

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 3165K	Veh. Inspected	SGW 4416D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/066 (LK)	Excess (\$)	0.00
Assign From	YAP RAY KAI JOEL	Assign Date	31/12/2024

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SWIFT 1.6 MT	c.c	1586
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JSAEZC31S00200051	Colour	WHITE
Odometer	301369 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50R16	GOFORM	5 mm
L/H Front Tyre	205/50R16	GOFORM	5 mm
R/H Rear Tyre	205/50R16	GOFORM	5 mm
L/H Rear Tyre	205/50R16	GOFORM	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/12/2024	Inspect Date / Time	31/12/2024 (12:21 PM)
Survey held at	EVEREST MOTORWERKZ PTE LTD 10 KAKI BUKIT RD 2 #03-18 SINGAPORE 417868		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days