

Not Withheld
 Penny Bepain
 3 days
 1/1mp @ 7600/

VEHICLE NO: SNM3516A
 CHASSIS NO: ZWR90-0027917

MODEL: TOYOTA NOAH

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER RHS <i>600</i>	<i>my</i> \$ 700.00 <i>2</i>
FRONT BUMPER RETAINER RHS	\$ <i>in</i> 140.00 <i>X</i>
FRONT HEADLAMP RHS <i>3985</i>	<i>my</i> \$ 4,400.00 <i>2</i>
HEADLAMP BRACKET RHS	\$ <i>in</i> 80.00 <i>X</i>
SUPPORT PANEL	\$ <i>in</i> 1,900.00 <i>X</i>
FRONT REINFORCEMENT	\$ <i>in</i> 750.00 <i>X</i>
FRONT FENDER RHS	\$ <i>in</i> 1,250.00 <i>X</i>
FRONT FENDER INNER SHIELD RHS	\$ <i>in</i> 400.00 <i>X</i>
FRONT BONNET	\$ <i>in</i> 1,070.00 <i>X</i>
BONNET HINGE RHS	\$ <i>in</i> 80.00 <i>X</i>
FRONT SENSORS X 2 (@ \$500 EACH) <i>048340</i>	<i>nd</i> \$ 1,000.00 <i>2+</i>
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	
	\$ 11,770.00
	\$ 2,942.50
	\$ 8,827.50
<u>SPECIAL NETT ITEMS</u>	
FRONT BUMPER CLIPS 1 SET	\$ <i>in</i> 60.00 <i>✓</i>
FRONT CARPLATE W/HOLDER	\$ <i>in</i> 120.00 <i>X</i>
MODELLISTA FRONT LOWER LIP <i>P17</i>	<i>CM</i> \$ 1,600.00 <i>✓</i>
MODELLISTA FRONT GRILLE KIT <i>P11</i>	<i>CM</i> \$ 1,800.00 <i>✓</i>
MODELLISTA ILLUMINATION BLADE <i>P17</i>	\$ <i>in</i> 1,600.00 <i>✓</i>
BODYKIT SEALEANT	\$ <i>in</i> 60.00 <i>3052</i>
Total	\$ 5,240.00
TOTAL PARTS	\$ 14,067.50

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	2501
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	1801
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	201
4	To provide anti-rust treatment on affected areas	\$ ~ 100.00	X
5	Dignostic Check	\$ ~ 100.00	X
6	Remove & refit front sensors	\$ 100.00	501
	Labour Total :	\$ 3,600.00	
	TOTAL (PARTS & LABOUR):	\$ 17,667.50	

VEHICLE NO: SNM3516A
CHASSIS NO: ZWR90-0027917

[illegible]

LABOUR			
		TOTAL:	\$ -
(LABOUR + PARTS) TOTAL:			\$ 135.00