



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SFC 9600Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE	BENT	\$1,219.62	\$1,219.62
1	REAR TAILGATE "TESLA" EMBLEM	NECESSARY	\$48.59	\$48.59
1	REAR TAILGATE INNER TRIM BOARD	SERVICEABLE	\$116.82	\$0.00
1	REAR BUMPER	BUCKLED	\$836.45	\$836.45
1	RAER BUMPER LOWER LIP	DENTED/CUT	\$542.05	\$542.05
1	REAR BUMPER LOWER LIP CENTER COVER	SERVICEABLE	\$20.56	\$0.00
1	REAR BUMPER REFLECTOR LH	CRACKED	\$40.18	\$40.18
1	REAR BUMPER SIDE BRACKET LH	TO REPAIR SEE LABOUR	\$5.60	\$0.00
1	REAR BUMPER REINFORCEMENT	BENT	\$299.06	\$299.06
1	REAR BUMPER CENTER BRACKET	CRACKED	\$8.41	\$8.41
1	REAR BUMPER PARKING SENSOR	SERVICEABLE	\$158.87	\$0.00
1	REAR BUMPER PARKING SENSOR BRACKET	TO REPAIR SEE LABOUR	\$6.54	\$0.00
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 10.00% DISCOUNT		(\$330.28)	(\$299.44)
			\$2,972.47	\$2,694.92

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$100.00	\$40.00
1	REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
			\$200.00	\$140.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE BRACKET LH, REAR BUMPER PARKING SENSOR BRACKET AND REAR END PANEL.		\$700.00	\$400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC		\$700.00	\$440.00
	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC		\$150.00	\$120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS	NOT NECESSARY	\$120.00	\$60.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC		\$120.00	\$60.00
	TO TUFF KOTE & UNDERSEAL MATERIALS		\$120.00	\$30.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY		\$200.00	\$0.00
	TO CHECK WIRING & ELECTRICAL SYSTEM		\$120.00	\$20.00
	PPF FOR AFFECTED AREAS		\$1,850.00	\$1,750.00
			\$4,080.00	\$2,880.00
GRAND TOTAL			\$7,252.47	\$5,714.92
	RECOMMENDED COST OF REPAIRS			\$5,714.92
Report Ref No: CS/AGI24070047/Kvh3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.