

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24070041/TNP3E2**Date:** 16/07/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP006154
Claimant Vehicle No :	SHC3231U	Insured Vehicle No :	GBF5607L
Date of Loss:	30/06/2024	Nature of Claim:	TP
		Claim No:	M2403658

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3231U		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU080996
Reg. Date:	03/09/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU107448
Colour:	Blue	Odometer:	885836 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,279.40	2,460.28	819.12	24.98
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	740.00	690.00	50.00	6.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,031.40	3,162.28	869.12	21.56
Approved Total (Overridden) (\$\$)		2,550.00		
(\$\$)	4,031.40	2,550.00	1,481.40	36.75
+ GST 9.00/9.00% (\$\$)	362.83	229.50	133.33	36.75
Nett Amount (\$\$)	4,394.23	2,779.50	1,614.73	36.75

INSPECTION

Date of Assignment:	02/07/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/07/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2024)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3231U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	481.10 FL	*481.10 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER UPPER MOULDING	Cut	368.50 FL	*368.50 FL
4	1		*FRT BUMPER SIDE BRKT RH	Not Necessary	35.00 FL	*- FL
5	1		*HEADLAMP RH	Cut	2,110.30 FL	*2,110.30 FL
6	1		*DAYLIGHT RH	Not Necessary	642.50 FL	*- FL
7	1		*DAYLIGHT GRILLE RH	Cut	93.45 FL	*93.45 FL
8	1		*FRT WHEEL CAP RH	Not Necessary	346.40 FL	*- FL
					Sub Total (\$\$)	4,099.25 3,075.35
					- List Item Discount on L Items 20.00/20.00% (\$\$)	819.85 615.07
					Total Parts (\$\$)	3,279.40 2,460.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	CHECK LIGHTINGS	New	40.00	30.00
Gross Labour Cost (\$)			740.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >