

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24070048/TNP3E2**Date:** 16/07/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SHC313L **Insured Vehicle No :** SJZ3827G

Date of Loss: 28/06/2024 Nature of Claim: TP Claim No: DMPC2400815H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC313L**

Make & Model: HYUNDAI IONIQ, 1.6 (A) Engine No: G4LEKU389507

Reg. Date: 27/08/2020 (Man. Year: 2019) Chassis No: KMHCH851CVLU184492

Colour: Yellow Odometer: 472663 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,540.56	416.00	1,124.56	73.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	690.00	90.00	11.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,320.56</b>	<b>1,106.00</b>	<b>1,214.56</b>	<b>52.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>(S\$)</b>	2,320.56	900.00	1,420.56	61.22
<b>+ GST 9.00/9.00% (S\$)</b>	208.85	81.00	127.85	61.22
<b>Nett Amount (S\$)</b>	<b>2,529.41</b>	<b>981.00</b>	<b>1,548.41</b>	<b>61.22</b>

INSPECTION

Date of Assignment: 02/07/2024

Date Inspected: 02/07/2024 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2024)
Parts:	143	HYUNDAI IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC313L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
2	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
6	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
7	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 FS	*55.00 FS
8	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
9	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	1,854.45 506.25
					- List Item Discount on L Items 20.00/20.00% (\$)	313.89 90.25
					Total Parts (\$)	1,540.56 416.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>780.00</b>	<b>690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >