COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC313L

Make

: HYUNDAI

Model

: IONIQ(G3)

Date: 01/07/2024

Insurance: ECICS

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40 RX
10	REAR BUMPER CLIPS			\$22.00
•	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
	1 REAR BUMPER REINFORCEMENT			\$394.80
	1 ANTENNA SMARTKEY			\$40.50 X
	1 REAR BUMPER FOG LAMP			\$201.50 X
			451.25	
			20/ 361	
	SUB TOTAL	_		\$1,569.45
	LESS 20%	6		\$313.89
	DISCOUNTED TOTAL	-1		\$1,255.56
	REAR NUMBER PLATE WITH TRIM COVER			\$55.00 €
	REAR BUMPER RUBBER MAT	1	55	\$50.00
	REAR BUMPER REVERSE SENSOR	1	''	\$180.00
	REAR BUMPER REVERSE SENSOR		NETT	\$285.00
	Labour Charge		3.80	3.000
	PANEL BEATING		28	
	SPRAY PAINTING CHARGE		690	\$300.00
	REMOVE/REFIX REVERSE SENSOR		V	30 \$80.00
	TOTAL LABOU	R	1106	\$780.00
			415\$ 900	
	ESTIMATE TOTA	L	115\$ 900 ,2daysx	\$2,320.56
			, 2day 5 x	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Turphi 97495749

isp 2/7/24 e 12 pm

- 2days

L/5 resmy after report

taup'M e/hhantoim.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: