

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 4488M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DEFORMED / TORN	945.20	720.70
1	FRONT BUMPER SIDE RETAINER O/S (CONSISTENT)	CRACKED	66.50	38.20
1	FRONT BUMPER BEAM (CONSISTENT)	TO REPAIR SEE LABOUR	315.00	-
1	HEADLAMP O/S (CONSISTENT)	CRACKED	1,650.00	591.70
1	HEADLAMP LOWER GARNISH O/S (CONSISTENT)	TORN	605.00	445.80
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	588.10	-
1	FRONT FENDER O/S (CONSISTENT)	DENTED	645.10	610.70
1	FRONT FENDER INNER SHIELD O/S (CONSISTENT)	SERVICEABLE	182.50	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,266.00	-
	LESS 10% DISCOUNT		-626.34	-240.71
			5,637.06	2,166.39
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIPS O/S (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BONNET SEALANT (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
			110.00	30.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING .		60.00	30.00
	TO REFILL AIR CON GAS .	NOT NECESSARY	120.00	-
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		180.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BEAM AND BONNET.		800.00	480.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	550.00
			2,390.00	1,130.00
	GRAND TOTAL		8,137.06	3,326.39

Report Ref No. CC4/ASM22005552/Upa3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			3,326.39
-----------------------------	--	--	----------

Report Ref No. CC4/ASM22005552/Upa3q2

CHUA KANG SENG
Licensed Appraiser