



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 6141L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FENDER	DENTED	\$453.80	\$453.80
1	FRONT FENDER INNER SHIELD	TORN	\$132.50	\$132.50
1	FRONT FENDER QUARTER GARNISH	NOT NECESSARY	\$70.90	\$0.00
1	FRONT LOWER ARM	BENT	\$342.40	\$342.40
1	FRONT SHOCK ABSORBER	NOT NECESSARY	\$291.60	\$0.00
1	FRONT WHEEL HUB C/W BEARING	DAMAGED	\$278.10	\$278.10
1	FRONT KNUCKLE ARM	DAMAGED	\$452.50	\$452.50
1	FRONT DOOR	DENTED	\$852.90	\$852.90
1	FRONT DOOR LOCK	NOT NECESSARY	\$176.20	\$0.00
1	FRONT DOOR WEATHERSTRIPE	NOT NECESSARY	\$165.40	\$0.00
1	FRONT DOOR GLASS REGULATOR GEAR	NOT NECESSARY	\$273.80	\$0.00
1	FRONT DOOR GLASS REGULATOR MOTOR	NOT NECESSARY	\$390.40	\$0.00
1	FRONT DOOR INNER TRIM BOARD	NOT NECESSARY	\$395.40	\$0.00
1	REAR DOOR	TO REPAIR SEE LABOUR	\$894.50	\$0.00
1	REAR DOOR LOCK	NOT NECESSARY	\$190.60	\$0.00
1	REAR DOOR WEATHERSTRIPE	NOT NECESSARY	\$178.80	\$0.00
	<b>LESS 20.00% DISCOUNT</b>		(\$1,107.96)	(\$502.44)
			<b>\$4,431.84</b>	<b>\$2,009.76</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	\$30.00	\$30.00
1	FRONT WHEEL RIM (SN)	CUT	\$680.00	\$400.00
1	FRONT TYRE (SN)	NOT NECESSARY	\$250.00	\$0.00
1	SET FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
1	FRONT DOOR SPEAKER (SN)	NOT NECESSARY	\$280.00	\$0.00
1	FRONT DOOR BLACK TAPE (SN)	NECESSARY	\$100.00	\$60.00
1	REAR DOOR BLACK TAPE (SN)	NOT NECESSARY	\$100.00	\$0.00
1	REAR WHEEL RIM (SN)	NOT NECESSARY	\$680.00	\$0.00
1	REAR TYRE (SN)	NOT NECESSARY	\$280.00	\$0.00
			<b>\$2,430.00</b>	<b>\$490.00</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR	NOT NECESSARY	\$1,200.00	\$400.00
	SPRAY PAINTING		\$1,000.00	\$600.00
	WIRING		\$50.00	\$30.00
	TO APPLY TUFF COAT		\$150.00	\$30.00
	TO REMOVE UPHOLSTERY		\$150.00	\$0.00
	TO TRANSFER FRONT & REAR DOOR FITTINGS		\$300.00	\$60.00
	TO REMOVE FRONT UNDERCARRIAGE		\$350.00	\$180.00
	TO PERFORM WHEEL ALIGNMENT		\$150.00	\$80.00
			\$3,350.00	\$1,380.00
GRAND TOTAL			\$10,211.84	\$3,879.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,100.00	
Report Ref No: CS/AGI24070051/Anh3m4				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.