

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24070055/AMA3Q2**Date:** 12/11/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0007413  
**Claimant Vehicle No :** SMQ8259A **Insured Vehicle No :** SLQ3155K  
Date of Loss: 01/07/2024 Nature of Claim: TP Claim No: MFL2024D0007694

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMQ8259A**  
Make & Model: TOYOTA SIENTA HYBRID, 1.5 X 7 SEATER CVT (A) Engine No: 1NZR808197  
Reg. Date: 03/12/2019 (Man. Year: 2019) Chassis No: NHP1707181269  
Colour: White Odometer: 326891 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm  
Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,282.17	3,018.17	1,264.00	29.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,470.00	1,580.00	890.00	36.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,752.17</b>	<b>4,598.17</b>	<b>2,154.00</b>	<b>31.90</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	6,752.17	3,600.00	3,152.17	46.68
<b>+ GST 9.00/9.00% (S\$)</b>	607.70	324.00	283.70	46.68
<b>Nett Amount (S\$)</b>	<b>7,359.87</b>	<b>3,924.00</b>	<b>3,435.87</b>	<b>46.68</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 9.00% GST) (S\$)</b>		436.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>4,387.25</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,380.00</b>		

**INSPECTION**

Date of Assignment: 03/07/2024  
Date Inspected: 03/07/2024 Inspected At: Twincar Automotive Pte Ltd (HQ)  
2 KAKI BUKIT AVEUNE 2 #01-17  
Singapore 417921  
Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2024)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X 7 SEATER CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ8259A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	750.00 FL	*495.00 FL
2	1		*REAR BUMPER CENTER PROTECTOR GARNISH	Deformed	207.00 FL	*207.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	170.00 FL	*- FL
4	2		*REAR BUMPER SIDE PROTECTOR GARNISH L/R	Not Necessary	302.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	180.00 FL	*- FL
6	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	25.00 FL	*- FL
7	1		*REAR END OUTER PANEL	Dented	533.60 FL	*533.60 FL
8	1		*REAR END PANEL KEY ANTENNA SENSOR	Cracked	127.00 FL	*127.00 FL
9	1		*REAR END PANEL TOP GARNISH	Cracked	207.00 FL	*207.00 FL
10	1		*REAR TAILGATE	Dented	1,131.90 FL	*1,131.90 FL
11	1		*REAR TAILGATE LOGO EMBLEM	Necessary	79.40 FL	*79.40 FL
12	2		*REAR TAILGATE HINGES L/R	Not Necessary	156.00 FL	*- FL
13	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	38.00 FL	*- FL
14	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	38.00 FL	*- FL
15	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	208.00 FL	*- FL
16	1		*REAR TAILGATE MECHANISM LOCK	Damaged	265.00 FL	*265.00 FL
17	1		*REAR TAILGATE WEATHERSTRIP	Cut	385.00 FL	*385.00 FL
18	2		*REAR TAILGATE WINDSCREEN MOULDING L/R	Necessary	90.00 FL	*90.00 FL
19	2		*REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER)	Necessary	90.00 FL	*90.00 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
22	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
23	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
25	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
27	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
Sub Total (\$)						5,527.90 3,920.90
- List Item Discount on L Items 25.00/25.00% (\$)						1,245.73 902.73
Total Parts (\$)						4,282.17 3,018.17

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	60.00
4	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,470.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >