



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: HARMINDER		Ref: CS/FCI24060037/Tnp3e2(N) Date: 04/02/2025 Code: FCI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SG 5952H
Policy No.	D-24102356MFBP	Coverage (\$)	0.00
Claim No.	D24005071MFBP	Excess (\$)	0.00
Assign From	HARMINDER	Assign Date	11/06/2025
2. Vehicle Particulars & Condition			
Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WMAA95ZZ9JF007409	Colour	GREEN
Odometer	516455 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/06/2024	Inspection Date	11/06/2024
Survey held at	MANDAI DEPOT		
Repairer	TOWER TRANSIT SINGAPORE PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		80 Working Days	