



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNJ 8969J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT/TORN	\$2,690.40	\$2,690.40
2	FRONT BUMPER BRACKET O/S @ \$206.70	NOT NECESSARY	\$413.40	\$0.00
2	FRONT BUMPER SIDE RETAINER O/S @ \$203.40	NOT NECESSARY	\$406.80	\$0.00
2	FRONT BUMPER CHROME (LONG) O/S LH & RH @ \$1,290.80	N/S SCRATCHED / O/S NOT NECESSARY	\$2,581.60	\$1,290.80
2	FRONT BUMPER CHROME BRACKET LH & RH @ \$325.50	NOT NECESSARY	\$651.00	\$0.00
1	HEADLAMP ASSY LED LH	HOLDER CRACKED	\$4,980.90	\$4,980.90
1	HEADLAMP LOWER BRACKET O/S LH & RH @ \$345.60	NOT NECESSARY	\$345.60	\$0.00
2	FRONT BUMPER CHROME SHORT SET LH & RH @ \$1,080.90	NOT NECESSARY	\$2,161.80	\$0.00
1	FRONT FENDER INNER SHIELD O/S LHS	NOT NECESSARY	\$303.60	\$0.00
1	SET FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	\$80.00	\$0.00
1	FRONT GRILLE SET WITH CHROME	* CHECK	\$3,960.50	\$0.00
2	FRONT BUMPER COVER HOLE LH & RH @ \$560.50	NOT NECESSARY	\$1,121.00	\$0.00
2	FRONT BUMPER SENSOR @ \$435.50	SERVICEABLE	\$871.00	\$0.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	\$986.60	\$0.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$1,680.60	\$0.00
1	FRONT BUMPER FOAM	NOT NECESSARY	\$568.40	\$0.00
1	FRONT BUMPER INNER SPOILER BRACKET	NOT NECESSARY	\$1,360.60	\$0.00
1	TOWING COVER	NOT NECESSARY	\$135.60	\$0.00
1	FRONT FENDER LH	DENTED/BENT	\$1,095.40	\$1,095.40
1	WHEEL RIM	CUT/WARPED	\$1,200.00	\$1,200.00
	LESS 25.00% DISCOUNT		(\$6,898.70)	(\$2,814.38)
			\$20,696.10	\$8,443.12

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$60.00	\$30.00
1	MISCELLANEOUS ITEM (SN)	NOT NECESSARY	\$60.00	\$0.00
			\$120.00	\$30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS		\$2,000.00	\$520.00
	TO PUTTY, SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS		\$1,800.00	\$800.00
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT		\$150.00	\$60.00
	TO REMOVE AND REINSTALL WIRE HARNESS. CHECK ACCORDING TO DAMAGE		\$200.00	\$20.00
	TO CONDUCT & RESET ECU DIAGNOSTIC PROGRAMME		\$450.00	\$0.00
			\$4,600.00	\$1,400.00
GRAND TOTAL			\$25,416.10	\$9,873.12
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,420.38 NETT)			\$9,873.12
Report Ref No: CS/FCI24070057/Uvp3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.