

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070058/ANP3E2
Date: 25/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	YQ5863H	Insured Vehicle No :	SLJ4685C
Date of Loss:	01/07/2024	Nature of Claim:	TP
		Claim No:	DMPC2400814H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ5863H	Engine No:	1GD8878403
Make & Model:	TOYOTA DYNA 150, 2.8 D 5MT (M)	Chassis No:	JHHAGV4600K001825
Reg. Date:	24/02/2022 (Man. Year: 2022)	Odometer:	32147 km
Colour:	Silver		
Engine Capacity:	2755 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	175/75 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,423.85	8,245.80	15,178.05	64.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,230.00	2,100.00	5,130.00	70.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,653.85	10,345.80	20,308.05	66.25
Approved Total (Overridden) (S\$)		8,250.00		
(S\$)	30,653.85	8,250.00	22,403.85	73.09
+ GST 9.00/9.00% (S\$)	2,758.85	742.50	2,016.35	73.09
Nett Amount (S\$)	33,412.70	8,992.50	24,420.20	73.09

INSPECTION

Date of Assignment:	02/07/2024	
Date Inspected:	30/07/2024	Inspected At: JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Oct 2024)	
Parts:	N/A	TOYOTA DYNA 150 2.8 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ5863H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	727.10 FL	*727.10 FL
2	2		*FRONT BUMPER BRACKET	Not Necessary	425.40 FL	*- FL
3	2		*HEAD LAMP	Cracked	1,994.60 FL	*1,994.60 FL
4	2		*HEAD LAMP LOWER RUBBER	Not Necessary	94.40 FL	*- FL
5	1		*FRONT CHASSIS CROSS MEMBER	Repair	958.00 FL	*- FL
6	1		*FRONT GRILLE	Cracked	479.80 FL	*479.80 FL
7	1		*FRONT GRILLE LOGO	Necessary	78.00 FL	*78.00 FL
8	1		*TAILGATE	Dented	1,370.00 FL	*1,370.00 FL
9	4		*TAILGATE HINGE	Not Necessary	660.00 FL	*- FL
10	1		*TAILGATE SIDE LOCK	N/S Damaged	250.00 FL	*125.00 FL
11	1		*TAILGATE STOPPER RUBBER	N/S Missing	70.00 FL	*35.00 FL
12	1		*TAILGATE STOPPER BRACKET	N/S Bent	350.00 FL	*175.00 FL
13	1		*TAILGATE STICKER TOYOTA	Not Necessary	167.60 FL	*- FL
14	1		*TAILGATE STICKER CHINESE WORDS	Not Necessary	50.00 FL	*- FL
15	1		*SIDE GATE LH	N/S Dented	3,937.80 FL	*1,968.90 FL
16	1		*SIDE GATE SAFETY LOCK LH	Not Necessary	132.10 FL	*- FL
17	1		*REAR CARGO BED SIDE PANEL LH	Repair	2,385.00 FL	*- FL
18	1		*TAIL LAMP LH	Cracked	245.00 FL	*245.00 FL
19	1		*TAIL LAMP SUPPORT BRACKET LH	Bent	185.00 FL	*185.00 FL
20	1		*TAIL LAMP LOWER REFLECTOR LH	Cracked	86.00 FL	*86.00 FL
21	1		*REAR STICKER DYNA	Necessary	45.00 FL	*45.00 FL
22	1		*REAR END PANEL	Repair	1,245.00 FL	*- FL
23	1		*REAR REINFORCEMENT	Dented	2,200.00 FL	*1,200.00 FL
24	2		*REAR REINFORCEMENT BRACKET	Not Necessary	1,136.00 FL	*- FL
25	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
26	1		*SET FRONT GRILLE CLIP	Necessary	40.00 FS	*30.00 FS
27	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1		*TAIL GATE 60KM/H STICKER	Necessary	40.00 FS	*15.00 FS
29	1		*TAIL GATE 13PAX STICKER	Necessary	40.00 FS	*15.00 FS
30	1		*TAIL GATE COMPANY STICKER (SPECIAL TYPE)	Necessary	550.00 FS	*250.00 FS
31	1		*TAIL GATE COVER (ALUMINIUM)	Bent	1,000.00 FS	*400.00 FS
32	1		*SIDE GATE STICKER (SPECIAL TYPE)	Necessary	800.00 FS	*250.00 FS
33	1		*SIDE GATE COVER (ALUMINIUM)	Dented	1,800.00 FS	*500.00 FS
34	1		*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
35	1		*REAR STEP BRACKET	Not Necessary	80.00 FS	*- FS
36	1		*REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE)	Not Necessary	3,800.00 FS	*- FS
37	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
38	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,241.80	10,424.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,817.95	2,178.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$)	23,423.85
						8,245.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK (FRONT)	New	1,200.00	300.00
2	TO PUTTY, SPRAY PAINT, POLISH WAX (FRONT)	New	1,000.00	400.00
3	TO SPRAY TUFF COAT (FRONT)	New	250.00	0.00
4	WIRING, BULB CHECKING (FRONT)	New	80.00	30.00
5	CONDUCT WATER TER LEAKAGE TEST (FRONT)	New	80.00	0.00
6	REFOCUS HEADLAMP BEAM (FRONT)	New	60.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC (FRONT)	New	180.00	0.00
8	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK (REAR)	New	1,800.00	600.00
9	TO PUTTY, SPRAY PAINT, POLISH WAX (REAR)	New	1,400.00	600.00
10	REMOVE AND REFIX REVERSE SENSOR (REAR)	New	80.00	50.00
11	REMOVE AND REFIX REAR FLOOR ALUMINIUM (REAR)	New	650.00	0.00
12	REMOVE AND REFIX TAILGATE AND SIDE GATE ALUMINIUM (REAR)	New	450.00	120.00
Gross Labour Cost (\$\$)			7,230.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >