

REF:

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / TP / TP RES / OD RES / EVA / INV / MVTo In Vehicle No: _____at Work / Site / Home / Other _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YQ5863H Yr Regn: 2022 FebType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.D. 2755Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 32147 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHHAGV4600K001825Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/75R15R: 175/75R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 30/07/24Survey held at JL PerfectDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP RECS</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>7786</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Addl Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Inve (\$

Survey Fee: _____

Transportation: _____

S + RS: \$1

Photos

Others

Report Format: _____

Report Form: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 29.07.2024

TO : ECICS MOTOR CLAIMS DEPTS
VEHICLE NO : YQ5863H
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 01.07.2024
TIME OF ACCIDENT : 09:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 727.10	\$ 727.10
2	FRONT BUMPER BRACKET <i>new</i>	2	\$ 212.70	\$ 425.40
3	HEAD LAMP <i>Replaced</i>	2	\$ 997.30	\$ 1,994.60
4	HEAD LAMP LOWER RUBBER <i>new</i>	2	\$ 47.20	\$ 94.40
5	FRONT CHASSIS CROSS MEMBER <i>Repair</i>	1	\$ 958.00	\$ 958.00
6	FRONT GRILLE <i>Replaced</i>	1	\$ 479.80	\$ 479.80
7	FRONT GRILLE LOGO <i>new</i>	1	\$ 78.00	\$ 78.00
8	TAILGATE <i>Replaced</i>	1	\$ 1,370.00	\$ 1,370.00
9	TAILGATE HINGE <i>new</i>	4	\$ 165.00	\$ 660.00
10	TAILGATE SIDE LOCK <i>LH Damaged</i>	2	\$ 125.00	\$ 250.00
11	TAILGATE STOPPER RUBBER <i>Missing LH</i>	2	\$ 35.00	\$ 70.00
12	TAILGATE STOPPER BRACKET <i>Best LH</i>	2	\$ 175.00	\$ 350.00
13	TAILGATE STICKER 'TOYOTA' <i>new</i>	1	\$ 167.60	\$ 167.60
14	TAILGATE STICKER 'CHINESE WORDS' <i>new</i>	1	\$ 50.00	\$ 50.00
15	SIDE GATE LH <i>Replaced LH</i>	2	\$ 1,968.90	\$ 3,937.80
16	SIDE GATE SAFETY LOCK LH <i>new</i>	1	\$ 132.10	\$ 132.10
17	REAR CARGO BED SIDE PANEL LH <i>Repair</i>	1	\$ 2,385.00	\$ 2,385.00
18	TAIL LAMP LH <i>Replaced</i>	1	\$ 245.00	\$ 245.00
19	TAIL LAMP SUPPORT BRACKET LH <i>Best</i>	1	\$ 185.00	\$ 185.00
20	TAIL LAMP LOWER REFLECTOR LH <i>Replaced</i>	1	\$ 86.00	\$ 86.00
21	REAR STICKER 'DYNA' <i>new</i>	1	\$ 45.00	\$ 45.00
22	REAR END PANEL <i>Repair</i>	1	\$ 1,245.00	\$ 1,245.00

New/old

1968.50

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **YQ5863H**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 01.07.2024
 TIME OF ACCIDENT : 09:20 HOURS

23	REAR REINFORCEMENT <i>Derived</i>	1	\$ 2,200.00	\$ 2,200.00	<i>900 12w</i>
24	REAR REINFORCEMENT BRACKET <i>new</i>	2	\$ 568.00	\$ 1,136.00	<i>+</i>

TOTAL PRICE \$ 19,271.80
 LESS 25% \$ 4,817.95
SUB TOTAL PRICE \$ 14,453.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>cut d</i>	1	\$ 50.00	\$ 50.00	<i>✓</i>
2	FRONT GRILLE CLIP (SET) <i>m</i>	1	\$ 40.00	\$ 40.00	<i>30</i>
3	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
4	TAIL GATE '60KM/H' STICKER <i>3 new</i>	1	\$ 40.00	\$ 40.00	<i>15</i>
5	TAIL GATE '13PAX' STICKER <i>1 new</i>	1	\$ 40.00	\$ 40.00	<i>15</i>
6	TAIL GATE COMPANY STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 550.00	\$ 550.00	<i>250</i>
7	TAIL GATE COVER (ALUMINIUM) <i>Beat</i>	1	\$ 1,000.00	\$ 1,000.00	<i>+ 400</i>
8	SIDE GATE STICKER (SPECAIL TYPE) <i>new</i>	1	\$ 800.00	\$ 800.00	<i>250</i>
9	SIDE GATE COVER (ALUMINIUM) <i>Derived</i>	1	\$ 1,800.00	\$ 1,800.00	<i>+ 500</i>
10	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
11	REAR STEP BRACKET <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
12	REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE) <i>new</i>	1	\$ 3,800.00	\$ 3,800.00	<i>+</i>
13	REAR REVERSE CAMERA <i>new</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
14	REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00	<i>2w</i>

TOTAL \$ 8,970.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD , CUT, ADJUST, KNOCK	\$ 1,200.00	<i>300</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,000.00	<i>400</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>x</i>
4	WIRING, BULB CHECKING	\$ 80.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	<i>x</i>

TO : **ECICS** MOTOR CLAIMS DEPTS
 VEHICLE NO : **YQ5863H**
 MODEL : **TOYOTA DYNA**
 DATE OF ACCIDENT : 01.07.2024
 TIME OF ACCIDENT : 09:20 HOURS

6	REFOCUS HEADLAMP BEAM	\$ 60.00	x
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD , CUT, ADJUST, KNOCK	\$ 1,800.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	600
4	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	50
5	REMOVE AND REFIX REAR FLOOR AUMINIUM	\$ 650.00	x
6	REMOVE AND REFIX TAILGATE AND SIDE GATE AUMINIUM	\$ 450.00	120

TOTAL \$ 7,230.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 23,423.85
 TOTAL LABOUR COST : \$ 7,230.00
 TOTAL REPAIR COST : \$ 30,653.85

*Adrian Lj
 r/s 30/07/24
 07 Days*

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: