

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 1642J

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER ASSY | DEFORMED | 1,265.00 | 689.00 |
| 1 | SET REAR BUMPER REFLECTOR | N/S CRACKED | 227.00 | 72.00 |
| 1 | REAR BUMPER REINFORCEMENT | NOT NECESSARY | 493.00 | - |
| 1 | REAR BUMPER TOW COVER | NOT NECESSARY | 85.00 | - |
| 1 | REAR WINDSCREEN GLASS | NOT NECESSARY | 1,420.00 | - |
| 1 | REAR WINDSCREEN GLASS MOULDING | NECESSARY | 188.00 | 188.00 |
| 1 | REAR TAILGATE ASSY | DENTED | 1,892.00 | 1,290.00 |
| 1 | REAR TAILGATE LOCK MECHANISM | DAMAGED | 245.00 | 245.00 |
| 1 | REAR TAILGATE INNER TRIM BOARD | CRACKED | 283.00 | 283.00 |
| 1 | REAR TAILGATE INNER HANDLE | NOT NECESSARY | 78.00 | - |
| 1 | REAR TAILGATE WEATHERSTRIP | NOT NECESSARY | 168.00 | - |
| 2 | REAR TAILGATE HINGES | NOT NECESSARY | 126.00 | - |
| 2 | REAR TAILGATE DAMPERS | NOT NECESSARY | 255.00 | - |
| 1 | REAR TAILGATE INNER LAMP | NOT NECESSARY | 65.00 | - |
| 1 | REAR TAILGATE NOTE EMBLEM | NECESSARY | 86.00 | 86.00 |
| 1 | REAR TAILGATE CENTRE LOGO | NECESSARY | 88.00 | 88.00 |
| 1 | REAR TAILGATE E POWER EMBLEM | NECESSARY | 87.00 | 87.00 |
| 1 | REAR RIGHT TAILLAMP | NOT NECESSARY | 655.00 | - |
| 1 | REAR LEFT TAILLAMP | CRACKED | 655.00 | 398.00 |
| 1 | REAR TAILGATE RIGHT TAILLAMP | CRACKED | 485.00 | 275.00 |
| 1 | REAR TAILGATE LEFT TAILLAMP | CRACKED | 485.00 | 275.00 |
| 1 | REAR TOOL KIT TRAY | NOT NECESSARY | 185.00 | - |
| 1 | REAR SPARE TYRE TOP COVER | NOT NECESSARY | 155.00 | - |
| 1 | REAR END LOWER PANEL | DENTED | 1,152.00 | 680.00 |
| 1 | REAR END LOWER PANEL TOP GARNISH | DEFORMED | 195.00 | 195.00 |
| 2 | REAR EXHAUST MUFFLER ASSY RUBBER MOUNTING | NOT NECESSARY | 65.00 | - |
| 1 | REAR EXHAUST MUFFLER ASSY | NOT NECESSARY | 1,250.00 | - |
| 1 | REAR LEFT FENDER INNER GARNISH | NOT NECESSARY | 315.00 | - |
| 1 | REAR RIGHT FENDER INNER GARNISH | NOT NECESSARY | 315.00 | - |

Report Ref No. CS/SMO24070061/Anp3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|----------------------|
| | LESS 10% DISCOUNT | | -1,296.30 | -485.10 |
| | | | 11,666.70 | 4,365.90 |
| | SPECIAL NETT ITEMS | | | |
| 16 | REAR BUMPER CLIPS (SN) | NECESSARY | 60.00 | 30.00 |
| 8 | REAR TAILGATE INNER TRIM BOARD CLIPS (SN) | NECESSARY | 50.00 | 30.00 |
| 1 | REAR END LOWER PANEL SEALANT (SN) | NECESSARY | 140.00 | 60.00 |
| 6 | REAR END LOWER PANEL TOP GARNISH CLIPS (SN) | NECESSARY | 40.00 | 20.00 |
| 8 | REAR LEFT FENDER INNER GARNISH CLIPS (SN) | NOT NECESSARY | 40.00 | - |
| 8 | REAR RIGHT FENDER INNER GARNISH CLIPS (SN) | NOT NECESSARY | 40.00 | - |
| 4 | REAR BUMPER REVERSE SENSOR (SN) | DAMAGED | 1,000.00 | 200.00 |
| 1 | REAR VIEW CAMERA (SN) | NOT NECESSARY | 450.00 | - |
| 1 | REAR NO PLATE WITH GARNISH (SN) | BENT | 100.00 | 60.00 |
| 1 | REAR WINDSCREEN GLASS SEALANT (SN) | NECESSARY | 100.00 | 60.00 |
| | | | 2,020.00 | 460.00 |
| | <u>LABOUR</u> | | | |
| | LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS. | | 1,400.00 | 800.00 |
| | TO PUTTY AND SPRAY PAINTING REAR PORTION. | | 1,400.00 | 800.00 |
| | TO REMOVE AND INSTALL REAR VIEW CAMERA. | | 80.00 | 50.00 |
| | TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM. | | 80.00 | 80.00 |
| | TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR. | | 150.00 | 80.00 |
| | TOWING SERVICE. | NOT NECESSARY | 100.00 | - |
| | TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY. | NOT NECESSARY | 120.00 | - |
| | TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA. | | 140.00 | 80.00 |
| | TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR. | | 80.00 | 50.00 |

Report Ref No. CS/SMO24070061/Anp3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|-------------------------------|-------------------|
| | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR. | | 140.00 | 120.00 |
| | | | 3,690.00 | 2,060.00 |
| | GRAND TOTAL | | 17,376.70 | 6,885.90 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 5,500.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/SMO24070061/Anp3m4(N)



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.