

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24070063/Anh3e2(N)	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	01/04/2025	
	ATTN: ENG HUEY	HUEY		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 2709M	Veh. Inspected	t	SMC 611S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1284210-002	Excess (\$)		0.00	
	Assign From	ENG HUEY HUEY	Assign Date		03/07/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALPHARD	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	ANH208101682	Colour		BLACK	
	Odometer	171814 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/50 R18	BRIDGESTONE		6 mm	
	L/H Front Tyre	235/50 R18	BRIDGESTONE		6 mm	
	R/H Rear Tyre	235/50 R18	BRIDGESTONE		6 mm	
	L/H Rear Tyre	235/50 R18	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/07/2024	Inspect Date /	Time	03/07/2024 (10:48 AM)	
	Survey held at	RYDER AUTO PTE LTD				
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				