

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: \_\_\_\_\_

OD / TP RES / OD RES / EVA / INV / MV

To in \_\_\_\_\_ Vehicle No: \_\_\_\_\_

at \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMC611S Yr Regn: 2010 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphard C.D. 2362

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 171814 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ANH20819682

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 03/07/24

Survey held at

Ryder

Des. of Damages: Front Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP INC

COE Expiry: 06/05/2030

MV: 96K

PV: 19.6K

Nett: 76.4K

Estimate given during: Yes ☒ / No ☐

1st Survey: Yes ☒ / No ☐

451A

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1) Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invt (\$)

Survey Fee:

Transportation:

8 + RS. \$1

Photos

Others

Report Form:

Report Form: