

(REPAIR COST NOT CONCLUDE)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBJ 6165S

REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	FRT DOOR RH	TO REPAIR SEE LABOUR	\$1,897.84	\$0.00	
2	FRT DOOR HINGE RH (TOP/LOWER) @\$157.20	NOT NECESSARY	\$314.40	\$0.00	
1	FRT DOOR CHECKER RH	NOT NECESSARY	\$264.50	\$0.00	
1	FRT HEADLAMP ASSY RH	CRACKED	\$1,239.80	\$1,239.80	
1	FRT BUMPER ASSY	DISTORTED	\$874.51	\$645.00	
1	FRT BUMPER SUPPORT	NOT NECESSARY	\$217.50	\$0.00	
1	FRT BUMPER BRACKET	NOT NECESSARY	\$431.60	\$0.00	
1	FRT FOGLAMP COVER RH	NOT NECESSARY	\$125.90	\$0.00	
1	FRT CORNER PANEL RH	TO REPAIR SEE LABOUR	\$336.80	\$0.00	
1	FRT GRILLE ASSY	NOT NECESSARY	\$695.20	\$0.00	
	LESS 25.00% DISCOUNT		(\$1,599.51)	(\$471.20)	
			\$4,798.54	\$1,413.60	
	Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	FRT BUMPER CLIPS (SN)	NECESSARY	\$30.00	\$30.00	
1	EDT DOOD COMPANY CTICKED (CN)				
	FRT DOOR COMPANY STICKER (SN)	NECESSARY	\$35.00	\$35.00	
	FRI DOOR COMPANY STICKER (SIN)	NECESSARY	\$35.00 \$65.00	\$35.00 \$65.00	
	Labo	I.	· · · · · · · · · · · · · · · · · · ·		
		I.	· · · · · · · · · · · · · · · · · · ·	\$65.00	
	Labo	our	\$65.00	\$65.00	
	Description of Parts TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT DOOR RH AND FRT CORNER	our	\$65.00 Workshop Estimate (\$)	\$65.00 Our Adjusted (\$)	
	Labo Description of Parts TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT DOOR RH AND FRT CORNER PANEL RH TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK	our	\$65.00 Workshop Estimate (\$) \$1,200.00	\$65.00 Our Adjusted (\$) \$400.00	
	Labo Description of Parts TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT DOOR RH AND FRT CORNER PANEL RH TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING TO PUTTY AND RESPRAY PAINTING ON FRT BUMPER, FRT CORNER PANEL RH, FRONT DOOR RH, FRT PANEL AND FRT	our	\$65.00 Workshop Estimate (\$) \$1,200.00 \$80.00	\$65.00 Our Adjusted (\$) \$400.00 \$30.00	
	Labo Description of Parts TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRT DOOR RH AND FRT CORNER PANEL RH TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING TO PUTTY AND RESPRAY PAINTING ON FRT BUMPER, FRT CORNER PANEL RH, FRONT DOOR RH, FRT PANEL AND FRT	our	\$65.00 Workshop Estimate (\$) \$1,200.00 \$80.00 \$1,000.00	\$65.00 Our Adjusted (\$) \$400.00 \$400.00	

Report Ref No: CS/INC24070065/Aqh3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

TOTAL FOR SPARE PARTS: \$ 4,863.54 \$ 1,478.60
TOTAL FOR LABOUR: \$ 2,280.00 \$ 830.00
TOTAL REPAIR COST: \$ 7,143.54 \$ 2,308.60

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.