

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 201400015E

ACORN MARKETING & SERVICES PTE. LTD.
BLK 512 CHAI CHEE LANE
02-09
SINGAPORE 469028
TEL : 6635 6147 FAX : 6635 6144
PH : 9366 4314 CINDY
ATTN :

Term:

ESTIMATE BILL

Number : EB00006534
Date : 10/06/2024
Case No : AD00014849
Vehicle No : GBH7905C
Chassis: JTFHT02P300245175
Year of Mfr 2018
Policy No 5103987494-05
Model : TOYOTA HIACE VAN
TURBO 5 DR

net Arthur
den
nera's
20/6/24
2/5 H.6000/
6 hrs
Euphrasie M. M.

Sn	DESCRIPTION	QTY	U PRICE	MANUAL DISC	AMOUNT
1	REAR SIDE PANEL RH	1.0	2,315.40	25	1,736.55
2	REAR LAMP RH	1.0	324.70	25	243.53
3	REAR LAMP LH	1.0	324.70	25	243.53
4	REAR LAMP LOWER GARNISH RH	1.0	127.70	25	95.78
5	REAR LAMP LOWER GARNISH LH	1.0	127.70	25	95.78
6	TAILGATE	1.0	2,293.20	25	1,719.90
7	TAILGATE LOCK	1.0	293.50	25	220.13
8	TAILGATE RUBBER	1.0	610.60	25	457.95
9	TAILGATE ABSORBER RH	1.0	321.10	25	240.83
10	TAILGATE ABSORBER LH	1.0	321.10	25	240.83
11	TAILGATE CENTER TRIMBOARD	1.0	246.10	25	184.58
12	TAILGATE EMBLEM	1.0	72.20	25	54.15
13	TAILGATE OUTER GARNISH	1.0	193.40	25	145.05
14	END PANEL INNER	1.0	1,172.50	25	879.38
15	END PANEL OUTER	1.0	466.10	25	349.58
16	END PANEL TOP GARNISH	1.0	143.70	25	107.78
17	REAR BUMPER	1.0	573.60	25	430.20
18	REAR BUMPER RETAINER RH	1.0	151.20	25	113.40
19	REAR BUMPER RETAINER LH	1.0	151.20	25	113.40
20	EXHAUST PIPE	1.0	570.60	25	427.95
21	REAR SPRING RH	1.0		25	
22	SPARE TYRE BRACKET	1.0	398.00	25	298.50
23	SPARE TYRE SCREW	1.0		25	
24	SPARE TYRE CHAIN	1.0		25	
25	EXHAUST PIPE MOUNTING	2.0	66.80	25	100.20
List Price - Parts Sub Total					8,498.98
26	TAILGATE STICKER - 70KM/H	1.0	30.00	0	30.00
27	TAILGATE CAMERA	1.0	650.00	0	650.00
28	REAR NUMBER PLATE	1.0	35.00	0	35.00
29	WINDSCREEN SEALANT	2.0	30.00	0	60.00
30	REVERSE SENSOR	1.0	300.00	0	300.00
31	REAR INNER SIDE PANEL RH - REPAIR	1.0			
32	REAR FLOOR PANEL - REPAIR	1.0			

E. & O. E.

Tail light housing panel RH 428.00
Rear air vent RH 98.00

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 201400015E

ACORN MARKETING & SERVICES PTE. LTD.
BLK 512 CHAI CHEE LANE
02-09
SINGAPORE 469028
TEL : 6635 6147 FAX : 6635 6144
PH : 9366 4314 CINDY
ATTN :

ESTIMATE BILL

Number : EB00006534
Date : 10/06/2024
Case No : AD00014849
Vehicle No : GBH7905C
Chassis: JTFHT02P300245175
Year of Mfr 2018
Policy No 5103987494-05
Model : TOYOTA HIACE VAN
TURBO 5 DR

Term:

Sn	DESCRIPTION	QTY	U_PRICE	MANUAL DISC	AMOUNT
Special Nett Price - Parts Sub Total					1,075.00
Parts Total					9,573.98
33	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,800.00	0 1200	1,800.00
34	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,500.00	0 1000	1,500.00
35	ANTI-RUST COATING	1.0	150.00	0 80	150.00
36	WIRING	1.0	100.00	0 20	100.00
37	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0 100	180.00
38	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0 30	150.00
Labour 1 Sub Total					3,880.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : FOURTEEN THOUSAND SIX HUNDRED SIXTY-FOUR AND CENTS EIGHTY-FOUR ONLY			Less Excess		0.00
			SUBTOTAL		13,453.98
			GST 9.00%		1,210.86
			TOTAL		14,664.84

Date of accident : 06/06/2024 01:00 PM. Place : BEDOK AVENUE TOWARDS BEDOK MALL

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

6437.40
252
4828.25
250
2480
7508.05
202
6096